Gary S. Graifman

KANTROWITZ, GOLDHAMER & GRAIFMAN, P.C.

210 Summit Avenue

Montvale, New Jersey 07645

Tel: (201) 391-7000 Fax: (201) 307-1086

UNITED STATES DISTRICT COURT FOR THE DISTRICT OF NEW JERSEY

GREG SUDDRETH, PAUL DUNTON, AND JOSEPH RICCA, On Behalf Of Themselves And All Others Similarly Situated,)) Civil Action No. 10-5130 (DMC)(JAD)
Plaintiffs,)
v.)
MERCEDES-BENZ USA, LLC)
Defendant.	
)

DECLARATION OF GARY S. GRAIFMAN IN SUPPORT OF MOTION FOR LEAVE TO FILE AMENDED COMPLAINT

GARY S. GRAIFMAN declares pursuant to 28 U.S.C. Sec. 1746, as follows:

- 1. I am a member of the firm Kantrowitz Goldhamer & Graifman, P.C., co-counsel for Plaintiffs in the above-captioned action and make this declaration in support of the motion for leave to file a Second Amended Class Action Complaint (also referred to as the "SAC"). The detailed factual allegations in the SAC submitted herewith cures those aspects of the prior complaint which the Court's order of October 31, 2011 found lacking.
- 2. A copy of the proposed Second Amended Class Action Complaint, together with exhibits thereto, is annexed hereto as Exhibit "A."

I declare under penalty of perjury that the foregoing is true and correct.

Executed this 1st day of December, 2011 in Monyale, New Jersey.

GARY S. GRAIFMAN

EXHIBIT A

UNITED STATES DISTRICT COURT FOR THE DISTRICT OF NEW JERSEY

GREG SUDDRETH, PAUL DUNTON, AND JOSEPH RICCA, On Behalf Of Themselves And)
All Others Similarly Situated,	Civil Action No. 10-5130 (DMC)(JAD)
Plaintiffs,) SECOND AMENDED CLASS) ACTION COMPLAINT
v.)
MERCEDES-BENZ USA, LLC) JURY TRIAL DEMANDED)
Defendant.)
	<u>,</u>

Following the Court's Order ("Order") dismissing Plaintiffs Greg Suddreth, Paul Dunton, and Joseph Ricca's (collectively "Plaintiffs") First Amended Complaint, Plaintiffs hereby file this Second Amended Complaint to address the grounds for dismissal raised in the Order.

NATURE OF THE ACTION

1. Plaintiffs Greg Suddreth, Paul Dunton, and Joseph Ricca bring this action on behalf of themselves and all other similarly situated owners and lessees of Mercedes Benz branded automobiles equipped with Mercedes' M272 or M273 engines¹ in the United States, as well as on behalf of subclasses of owners and lessees of these automobiles in Illinois,

¹Mercedes' M272 engine is a v-6 engine first introduced in 2004, and found in the following Mercedes model vehicles in the following model years: Mercedes C 230, SLK 280, SLK 350, and CLS 350 (2004 to present); E 230, CLS 280, CLK 280, C 280, E 280, SL 280, C 350, E 350, SL 350, and Viano (2005 to present); R 280, R 350, ML 350, and Sprinter (2006 to present); S 280 (2007 to present); CLC 230, and CLC 350 (2008 to present). Mercedes' M273 engine is a V-8 engine first introduced in the model year 2006, and found in the following Mercedes model vehicles in the following model years: E 500/E 550, CL 500/CL 550, CLS 500/CLS 550, and GL 500/GL 550 (2006); GL 450, S 450, and ML 450 (2007); ML 500/ML 550 (2008); and, CLK 500/CLK 550 (2006 and 2009). The class seeks to represent owners and lessees of the foregoing model vehicles who also meet the additional criteria set forth in paragraphs 36 of this Class Action Complaint.

Massachusetts, and New Jersey. As detailed, herein, the subject engines are equipped with defective gears in their balance shafts (in the event of the M272 engines) or with defective idle gears (in the case of the M273 engines). These defective gears wear out prematurely, excessively, and without warning, causing the vehicle to malfunction, the "check engine light" to remain illuminated, and the vehicle to misfire and/or stop driving. The only recourse is to have the balance shaft or idle gear replaced, which is a large scale repair job, taking numerous days and costing several thousand dollars. All the while, Defendant Mercedes-Benz USA, LLC ("Defendant" or "Mercedes") has known of the existence and manifestation of this defect, as is documented in its own internal documents, but has failed to take appropriate corrective or remedial action, and has concealed and affirmatively misreprented the existence of this defect from unsuspecting owners and lessees. Plaintiffs are among the numerous owners of such vehicles that have had faulty balance shaft or idle gears, and have incurred thousands of dollars' worth of repair bills as a result. Defendant's conduct with regards to the sale, distribution, and repair (or lack thereof) of these vehicles amounts to a violation of Defendant's common law and statutory duties, as detailed more fully herein.

JURISDICTION AND VENUE

- 2. This Court has subject matter over this action pursuant to the Class Action Fairness Act, 28 U.S.C. § 1332 (as amended 2005) because the Complaint pleads a class action involving more than \$5 million in controversy, and involves a putative plaintiff class or subclasses of diverse citizenship than Defendant.
- 3. This Court has personal jurisdiction over Defendant Mercedes-Benz USA, LLC because Defendant's principal place of business is located within this judicial district at 3 Mercedes Drive in Montvale, New Jersey 07645.

4. Venue is proper in this district because Defendant is located and headquartered within this judicial district, such that the injection of the subject vehicles into the United States' stream of commerce took place from within this judicial district. In addition, given Defendant's headquarters in this district, most or a significant amount of documentary evidence and likely witnesses are reasonably likely to be located within this judicial district. Venue in this district is therefore proper pursuant to 28 U.S.C. § 1391.

THE PARTIES AND THEIR EXPERIENCES

5. Plaintiff Greg Suddreth is a resident of Illinois, and an owner of a 2006 Mercedes ML-350 that he purchased from an authorized Mercedes dealer on approximately October 2006. The vehicle is equipped with Mercedes' M272 engine. On approximately February 2009, Plaintiff's vehicle began experiencing engine misfires, and had the "check engine light" illuminate without prior warning. Upon experiencing these issues, Plaintiff brought his vehicle in for repairs at the authorized Mercedes dealership. The dealership purported to repair the vehicle, kept it at the repair shop for approximately four weeks while repairs were being done, but in fact, failed to replace the vehicle's balance shaft, even though this was the actual cause of the vehicle's misfires and this problem was already known to Mercedes and its dealers. Shortly after receiving his vehicle back from the Mercedes dealership, Mr. Suddreth's vehicle again had its "check engine light" illuminate. Mr. Suddreth returned with his vehicle to the dealership's service department in November 2009. The Mercedes diagnostic scanner tool output a "Code 064," indicative of a problem with the vehicle's balance shaft, as had already been acknowledged in an internally disseminated Mercedes Technical Service Bulletin. Nevertheless, the dealership and Mercedes declined to replace the balance shaft, and demanded payment of \$500 just to "diagnose" the problem, even though Mercedes and its dealerships knew all along of the balance

shaft issues plaguing Mr. Suddreth's vehicle. The problems continued to persist. In February 2010, almost one year to the day since the symptoms first exhibited themselves, Mr. Suddreth's vehicle again began misfiring.

6. Unable to obtain satisfactory repair at the Mercedes dealership, Mr. Suddreth brought his vehicle to an independent Mercedes-Benz repair shop. That garage correctly diagnosed the source of the problem as a defective balance shaft gear that had worn prematurely and excessively. In addition, as a result of the ongoing wear on the balance shaft gears, the vehicle's cam sensor (which had already been replaced once by the Mercedes dealer) and air intake system had to be replaced, as metal shavings from the deteriorating balance shaft had been and were entering the air intake system. The independent Mercedes garage also showed Mr. Suddreth a Technical Service Bulletin that Mercedes had released internally to Mercedes technicians, acknowledging the problem with the balance shaft gears in the M272 engines. Replacement of the balance shaft, which was what was actually required, was to be an arduous and costly endeavor, and one for which the independent Mercedes repair shop was not equipped to undertake. Armed with this information, Mr. Suddreth returned with his vehicle to a Mercedes dealership. The dealership now confirmed that Mr. Suddreth's vehicle had a worn balance shaft gear that required replacement, and informed him that the repair would cost approximately \$6,000 and require several days' worth of work. Mercedes refused to cover the repair under the factory warranty, arguing that, as the vehicle had approximately 65,000 miles on it at the time of the defect's manifestation, the vehicle was now outside the warranty coverage term. This, despite the fact, that Mercedes had known all the while about the defect caused by its own making. Mr. Suddreth then contacted Mercedes Benz USA, LLC, but the representative to whom he spoke, Susan C., explicitly denied that there were any commonly occurring problems

or defects affecting the balance shafts in vehicles like the one owned by Mr. Suddreth. This representation was directly contradicted by the written Technical Service Bulletins issued internally by Mercedes, which acknowledged and described the problem. Mercedes refused to assist Mr. Suddreth or cover any cost of the needed repairs to his vehicle, and instead, the Mercedes dealership continued to demand the payment of money to diagnose the problem. To date, Mr. Suddreth has already expended several thousand dollars in repairs for his vehicle as a result of the alleged defect.

- 7. Plaintiff Paul Dunton is a resident of Massachusetts and the original owner of a 2006 Mercedes ML-350 that he purchased from an authorized Mercedes dealership. His vehicle is equipped with Mercedes' M272 engine. At some time in 2009, his vehicle's "check engine light" illuminated without prior warning, and the vehicle exhibited misfiring. As a result, Mr. Dunton's vehicle would not have passed Massachusetts' required state automobile inspection for renewal of its registration.
- 8. Mr. Dunton took his vehicle for repairs to an authorized Mercedes dealership.

 The dealership diagnosed the problem as a worn balance shaft gear that required replacement.

 Personnel at the Mercedes dealership confided to Mr. Dunton that this was a common problem known to Mercedes and affecting automobiles like his. The dealership informed Mr. Dunton that it would cost approximately \$4,200 to complete the required repairs. As a purported gesture of so-called "goodwill," recognizing the pervasiveness of this problem, the dealership agreed to contribute approximately \$2,100 towards the cost of the repair, leaving Mr. Dunton to pay the remaining \$2,100 approximate balance, which he did. The dealership took approximately 3 to 4 weeks total to complete the repairs. Subsequently, Mr. Dunton contacted Mercedes-Benz USA, LLC, but personnel there contradicted what the dealer informed him, and instead told Mr.

Dunton (falsely) that there were no common problems with the balance shafts in vehicles like his.

- 9. Plaintiff Joseph Ricca is a resident of Franklinville, New Jersey, and an owner of a 2006 Mercedes ML 350 that he purchased in approximately March 2009. The vehicle is equipped with Mercedes' M272 engine. When the vehicle was just 2 miles beyond the 50,000 mile warranty limit imposed by Mercedes, it began manifesting problems. Noticing certain code messages on his Mercedes display, Mr. Ricca researched the problem online and came to believe that the problems manifested by his car were related to the balance shaft gear. He contacted Mercedes Benz USA, LLC, as well as Mercedes of Cherry Hill, a Mercedes dealership. Eventually, after determining that the problems manifested with Mr. Ricca's car were, indeed, attributable to the defective balance shaft, Mercedes agreed to cover only \$2000 towards the cost of the replacement and repair. That left Mr. Ricca with an outstanding bill of approximately \$3300, which he paid to have his vehicle repair. When the vehicle repairs were done, the Mercedes technicians found that the balance shaft gears had, indeed, been stripped, indicating that the defect with the balance shaft had been developing over a period of time, including during the warranty period, during which period, the gears were damaged until Mr. Ricca began noticing the problems at the 50,002 mile mark. At no time prior to these occurrences, did Mercedes disclose or otherwise inform Mr. Ricca about the defects in the balance shaft of his car, nor did Mercedes disclose that this was a common problem seen in vehicles equipped with the M272 engine found in Mr. Ricca's car, even though damage was occurring to his vehicle's balance shaft gears...
 - 10. Defendant Mercedes-Benz USA, LLC is a limited liability corporation having its

principal place of business at 3 Mercedes Drive in Montvale, New Jersey 07645. Defendant is a subsidiary of Daimler, Inc., the manufacturer of Mercedes-branded vehicles. Founded in 1965, Mercedes-Benz USA, LLC is responsible for the distribution and marketing of Mercedes and Maybach automobiles within the United States. Defendant was the entity responsible for injecting the Mercedes vehicles currently owned by Plaintiffs into the United States stream of commerce.

THE PERVASIVE NATURE OF THE PROBLEM

- 11. Plaintiffs' experiences are but three of the many similar situations encountered by owners or lessees of M272 or M273 engine-equipped Mercedes vehicles in the United States. Upon information and belief, the defect in the subject vehicles appears to be attributable to a defect in the materials selection and/or the manufacture or design of the balance shaft gear (in the case of the M272 engines) or the idle gear (in the case of the M273 engines) that causes the sprockets on the balance shaft in the M272 engine to wear prematurely and excessively, and likewise to cause the guide on the idler gear that drives the timing chain in the M273 engine to wear prematurely and excessively. Indeed, so pervasive is the problem, that a host of message boards for aggrieved Mercedes owners have arisen online. Even a cursory sampling of these documents how pervasive the problem is.
- 12. Attached as Exhibit 1 hereto are postings at an online message board found at a website entitled benzworld.org. The message board topic begins with a posting of an owner of a 2006 Mercedes C230 with only 31,000 miles that had to have the balance shaft replaced. (Ex. 1 at p. 1). The reply postings reveal a steady stream of owners similarly affected. One poster relates that: "That's exactly what happened to mine. The CEL [check engine light] came on for both cams being out of time. When they tore the motor apart it turned out that the balance shaft

actually was worn causing it. Hopefully this won't happen again?" (Id.). Another owner posts that: "love my MB but am a real novice about anything automotive. CEL [check engine light] went on two days ago, brought it into MB and they told me that I needed to replace my balance shaft for a 06 E350 with 90k miles on it. Is this a common problem? I am being told it will take 3 days and \$4,000 to fix this which seems unbelievable when I have never had an issue with the car before." (Id. at 2). Another post (this one by Plaintiff Dunton), relates that, "The dealer told me I had the same problem with the balance shaft, and told me it was a common problem, they would fix it for \$4000 and mercedes would kick in \$2000 because it is a common problem." (Id.). Yet another posting (this one by Plaintiff Suddreth) relates that "Was just told by my mechanic I have this issue." (Id. at 4). Yet another poster to the same message board also informed that, "I was just informed that my 2006 e-350 needs to get the balance shaft replaced. Unfortunately, I am out of warranty; if they would have caught this problem 3 weeks ago when i brought it in for service, my warranty would have covered it." (Id. at 6). And the postings continue, as another owner describes that, "I am about to have a Gear on the balance shaft on my 2006 C240 replaced. The CEL [check engine light] stays on after servicing. Estimated at \$4000.00. Is this normal? I have 68,000 miles." (Id. at 7). Yet another aggrieved Mercedes owner posts that, "I have a 2006 ML350 with 56,000 miles at the dealer right now to replace the balance shaft. I've started a facebook page for owners who have had the same problems with that motor to get everyone together with this issue. Maybe a possible class action in the future??" (Id.).

13. The foregoing are but selected postings in only one online message boards, but the problem is so pervasive that several other online message boards with similar experiences exist. Another message board entitled "ML-350 3.5L Balance Shaft Failure" at the

peachparts.com site, attached hereto as Exhibit 2, contains the following posting from a Mercedes owner, "What a surprise!.. Wife's '06 ML350 had intermittent CEL [check engine light]. Last year, dealer replaced cam /timing position sensors. Problem continued to occur with CEL coming on even more frequently. NOW, they tell me that the Balance Shaft has a bad gear and it is deteriorating. 73K miles. Thank goodness for extended warranties. Finding from other web site threads and blogs that MB USA is not consistent with the treatment of customers... some customers are bearing the full cost of the repair while others are being offered "good will" discounts. Appears there had been a service bulletin out for 2 1/2 years on this problem with no sign that MBUSA is stepping up to cover a known fault. roughly 10 updates to the bulletin adding vehicles to the list." (Ex. 2 at 1). In response, a poster to the same message board that is evidently a Mercedes mechanic relates that, "I've got two at my shop right now, an ML and an R Class. It looks like two of my guys will be busy for the next few days. They're both out of warranty, but I'm sure MB will help out." (Id. at 3).

MERCEDES' ACTUAL KNOWLEDGE OF THE DEFECT, AND THE FACTS SUPPORTING THE ALLEGATIONS OF SUCH KNOWLEDGE

- 14. Mercedes has known all along about the existence of a defect with the balance shaft gears in its M272 engines and idle gears on its M273 engine, yet it has concealed that knowledge, deliberately omitted any information or dissemination about its existence to the unsuspecting putative class members, and beyond that has affirmatively misrepresented the reliability of vehicles equipped with the subject M272 and M273 engines so as to falsely convey the message that the vehicles were reliable and did not suffer from any reliability concerns known to Mercedes.
- 15. As documented in several automotive industry trade magazines, the problem at hand began with Mercedes M272 and M273 engines manufactured as early as 2004, and

prevailed in engines manufactured until September 2006. A news article in the German automotive magazine *Autobild*, dated August 4, 2011, which was entitled, "Mercedes Admits Material Fault," documents:

Owners of Mercedes six and eight cylinder engines still have to fear for their engines. Due to a material fault, on cars built between April 2004 until September 2006, a gearwheel of the timing chain can wear down. The damage is noticeable when the engine indicator lamp is on. Repairs cost up to 4700 Euros, depending on the model. Mercedes has built the engines of series M272 (2.5, 3 and 3.5 liter V6) and M273 (5 liter V8) in ten model ranges. It's still a mystery how many cars with M272 and M273 engines have been affected by this fault.

Exh. 3 hereto, at 1.2

16. The same German news article details that Mercedes was aware of the problem because it was caused by different steel compositions used in the part—a problem that Mercedes ultimately remedied in September 2006 by returning to a gear construction of conventional steel:

The reason: in case of chain wheels made of sintered steel, different material compositions are used. This problem was solved only after chain wheels were once again made of conventional steel (September 2006).

Id. at 2.

- 17. Not only that, but the *Autobild* German news report also details that, Mercedes has been well aware of the defect, and launched "an internal faults statistic which is, however, kept classified by Mercedes." *Id.* at 2.
- 18. Building on the news story first reported in the German magazine *Autobild*, the online automotive trade journal *Carfolio*, posted an article entitled "Mercedes Hit With Timing Chain Issues on 2004-2006 V6 and V8 Model," which likewise documented that:

Mercedes-Benz is currently trying to recapture the number one position in global luxury sales, but a quality problem on its home turf in Germany seems

² Exhibit 3 hereto is the translated English version of the *Autobild* news article. The original German version of the article is attached hereto as Exhibit 4.

to be undermining confidence in the brand. Autobild reports that the M272 V6 and M273 V8 engines used a sintered steel timing chain gear made of various materials starting in 2004, but switched to conventional steel in 2006, eliminating the problem with gear wear. The problem: nobody seems to know how many vehicles built between 2004 and 2006 are affected.

Exh. 5 hereto.

- 19. The same news article goes on to report that Mercedes had been well aware of the problem because it employed "secret internal defect tracking" in order to attempt to forecast the rate of failures that it could expect to see concerning the balance shaft gear-stripping. *Id*.
- 20. The report also detailed that, unlike in the United States, in Germany, Mercedes had acknowledged the problem and Mercedes' responsibility for it, by offering to cover free repairs to affected vehicles:

If you have a vehicle with one of these engines built between 04 and 06 and your check engine light comes on, Mercedes encourages you to visit your MB dealer rather than an independent shop, as Mercedes is offering free repairs to affected customers. And as Autobild's Matthias Mötsch argues, when your motto is "the best or nothing" the only answer to a situation like this is to fix 100% of the defects for free.

Id.

21. That the defect at issue plagued Mercedes M272 and M273 engines starting in 2004, and that Mercedes launched and kept undisclosed to the public or consumers an "internal fault statistic" or a "secret internal defect tracking" study to track the prevalence of the problems caused by this defect, and that Mercedes implemented a manufacturing change as of September 2006 (which necessarily must have been planned and approved before its actual production date and which pre-dated by a month plaintiff Suddreth's vehicle purchase) to remedy the defect by switching from sintered steel alloy to a conventional steel construction of the balance shaft gear, and that Mercedes has been offering consumers in Germany free repairs to remedy the defect, but has failed to do the same for consumers in the United States, are all facts supporting the

conclusion that Mercedes was well aware of the defect plaguing the engines powering Plaintiffs' vehicles prior to the Plaintiffs' purchases. Moreover, as detailed in paragraphs 31-35 below and the Exhibits referenced therein, Mercedes did more than merely fail to disclose its knowledge of this defect, but affirmatively misrepresented the reliability of the subject vehicles and the steps that Mercedes had taken purportedly to ensure that the vehicles that it knew were plagued by this defect, were reliable and had no quality concerns.

- 22. Though Mercedes' knowledge of the defect first came into being before Plaintiffs' purchases of their 2006 model year vehicles, Mercedes has continued to remain ever knowledgeable and mindful of the defect plaguing the M272 and M273 engines found in Plaintiffs' cars, but has continued concealing that knowledge and misrepresenting the attributes of Plaintiffs' vehicles. In August 2007, Mercedes issued an internal Technical Service Bulletin that documented the problem and informed Mercedes technicians how to diagnose it and replace the defective balance shaft or idle gears. Further, to date, since the August 2007 initial release of the internal Technical Service Bulletin, Mercedes has issued approximately 10 amendments, supplements or additional Technical Service Bulletins, all of which acknowledge the problem brought about by the defective balance shaft or idle gears.
- 23. The Technical Service Bulletins were disseminated internally by Mercedes to its repair technicians, and were not designed to and did not inform the general public, drivers, or lessees of affected vehicle about the defect. To the contrary, even while knowing all the while of the existence of this defect, Mercedes continued to offer for sale and sell the subject vehicles equipped with the M272 and M273 engines, and took no steps to replace the defective parts, or to otherwise remedy the defect.
 - 24. That Mercedes knew and has known all along about the defect in its balance shaft

gears is also independently confirmed by review of their diagnostic codes and manuals. When a Mercedes vehicle is brought in for repairs to an authorized Mercedes dealership, the technician may connect the vehicle to an electronic diagnostic scanner that will output a series of codes, which purport to store in the vehicle's computer memory a set of conditions that the vehicle has experienced. Armed with these codes, the Mercedes technician can turn to Mercedes repairs manuals that may document potential diagnoses of fault tree procedures to follow, given certain diagnostic code outputs from the scanner tool. For several years now, and even prior to Mercedes' issuance of its Technical Service Bulletin in mid-2007, Mercedes diagnostic manuals have alerted its technicians that in vehicles equipped with the M272 engine, if the scanner outputs codes that correspond to retarded cam shafts on the engine, the Mercedes diagnostic manual instructs the repair technician to check for probable balance shaft gear wear, thereby highlighting that Mercedes already knew of this defect, its symptoms, and manifestations, yet concealed its existence from the driving and buying public.

AS KNOWN TO MERCEDES AND THE INDUSTRY, THE EFFECT OF USING SINTERED STEEL WAS CERTAIN FAILURE OF THE PARTS

- 25. As documented in *Autobild*, the defect at issue was attributable to Mercedes' decision to manufacture the balance shaft gear and idle gear in the M272 and M273 engines, respectively, from sintered steel as opposed to conventional steel, starting in April 2004 until September 2006 (when Mercedes reverted to manufacturing the parts out of conventional steel). Sintered steel is a type of metal has undergone a sintering process, in which powdered metal is heated below its melting point until the particles form a molecular bond. Metals such as iron, copper, and aluminum are commonly turned into sintered steel.
- 26. Unlike traditional metallurgy, where steel is melted into a more or less liquid state before being shaped, sintered steel is forged while still in a powdered form. By not having to be

melted, several phases are eliminated from the conventional process. This reduces manufacturing time, and hence costs in high volume production.

- 27. The prospect of using sintered steel for engine components under high stress, like balance shaft gears and idle shaft gears, has been studied and reported at length in the literature. For years, it has been well known in the trade that, resort to parts made of sintered steel for engine components facing high stress (as is the case with idle shaft gears and balance shaft gears) would lead to premature failure because the parts manufactured out of sintered steel did not retain the stress bearing or fatigue characteristics of parts manufactured from conventional steel forging.
- 28. For example in a Technical Paper published in 1998 by the Society of Automotive Engineers ("SAE"), of which Mercedes is a member, researchers showed that engine parts made out of sintered steel had less fatigue strength than the same part made out of conventional forged steel. Similarly, another Technical Paper published by the SAE that same year documented that sintered steel engine parts are less reliable in meeting machined specifications. Yet another SAE Technical Paper published in 1988 had previously concluded that the fatigue properties of sintered steel engine parts could not be improved because of loss of microstructural heterogeneity in the composition of the parts. So too, in a published article in a treatise on metallurgy in automotive applications, researchers testing sintered steel automotive parts found that the sintered steel parts all failed due to corrosion fretting.
- 29. These studies and properties of sintered steel material for critical automotive parts were well known to the industry, and a subject of common study in professional societies of which Mercedes and its engineers were members. Despite these longstanding results and reports in the trade literature, Mercedes decided in 2004 to manufacture the balance shaft gears and idle

shaft gears in the M272 and M273 engines out of sintered steel. When it did so, Mercedes knew, given these longstanding studies and reports, that the parts were certain to fail.

30. The failure of an engine's balance shaft gear or idle shaft gear is a highly unusual occurrence in vehicles manufactured in the 21st century. It is extremely rare to see these failures in modern vehicles, much less is it commonplace to experience such failure in vehicles of the ages and mileage ranges of Plaintiffs' vehicles.

MERCEDES' AFFIRMATIVE REPRESENTATIONS CONCERNING VEHICLES EQUIPPED WITH THE SUBJECT ENGINES

- 31. Mercedes did more than merely fail to disclose its knowledge of the defect plaguing the M272 and M273 engines. Far from merely remaining silent (which would have been egregious enough), Mercedes undertook a campaign to affirmatively misrepresent the reliability and lack of quality concerns affecting Plaintiffs' cars, all at a time when Mercedes knew that the precise opposite was true.
- 32. For example, with the launch of the 2006 model year of its M-class line of vehicles, the cars were reviewed in the press as that year marked a purportedly redesigned version of the vehicles. As part of the press coverage, Mercedes spokespeople touted the supposed reliability of the vehicle, and specifically noted that any reliability issues that were of concern in the prior model years of the same vehicles were resolved with the 2006 model year lineup. In a review entitled, "2006 Mercedes-Benz M-Class" featured on the MSN network, Mercedes touted that:

Mercedes has had quality issues in the past few years, but feels confident that the new design of the solid-feeling M-class should be free of problems.

Ex. 6 at 2.

- 33. The same online news review of the 2006 M-class also quoted Mercedes spokesperson Rob Moran as acknowledging that "[t]he 2005 M-class [which Plaintiffs' 2006 model replaced] isn't unusually old for a Mercedes because the life cycle for most of our models is 7.5 years." *Id.* at 2.
- 34. The MSN network automotive review was just but one instance of Mercedes misrepresenting the reliability and quality attributes of its 2006 M-class vehicles. An online article on *CNN Money*, dated November 20, 2006, reported on Mercedes' response to the poor reliability ratings that Consumer Reports had assigned to the 2006 Mercedes vehicle lineup, as reported by owners of these cars. As documented in the CNN article, Consumer Reports found that:

Among mid-sized SUVs, the M-class, a quality disaster when it first came out, still ranks as the least reliable in its grouping.

Ex. 7, at 1.

35. Yet, when confronted with this reporting, and knowing full well that these vehicles were plagued by a defect in their balance shaft gears known only to Mercedes (recall that by November 2006—the date of the *CNN Money* article—Mercedes had already changed the manufacture of the balance shaft gear to conventional steel to deal with this undisclosed defect), Mercedes affirmatively responded by conveying the opposite impression as to the reliability and owner experience of the 2006 M-class lineup. The CNN article reported that "a spokesman for Mercedes says that the data in the *Consumer Reports* rankings 'is totally out of sync with what we're seeing in the mainstream research as well as our own customer satisfaction and warranty data." *Id.* at 1. In truth and in fact, by this time, the complaints about the balance shaft gear defect found in the 2006 M-class vehicles that Plaintiffs purchased were so pervasive that Mercedes had initiated a "secret internal defect tracking" study of the problem. It also initiated a

program in Germany where it began covering the cost of repairs for vehicles affected by this problem—something that it has not done in the United States.

CLASS ACTION ALLEGATIONS

- class action on behalf of all owners and lessees within the United States of Mercedes vehicles equipped with either the M272 or M273 engines, subject to the qualifications listed herein.

 Specifically, with respect to owners or lessees of Mercedes vehicles equipped with the M272, that portion of the class is limited to those owners of vehicles with M272 engines bearing serial numbers up to 2729..30 468993. With respect to owners or lessees of Mercedes vehicles equipped with the M273, that portion of the class is limited to those owners of vehicles with M273 engines bearing serial numbers up to 2739..30 088611. Collectively, the foregoing vehicles are referred herein as the "subject vehicles." Plaintiffs are both current owners of subject vehicles. Specifically excluded from the class are all judicial officers assigned to this case, as well as all federal and state employees, and the employees of Defendant or its corporate affiliates. Also excluded from the class definition are any individuals who allegedly have suffered personal injuries as a result of the alleged defects. Plaintiffs reserve to amend or supplement this class definition as discovery or other case development warrant.
- 37. In addition to the foregoing class definition, applicable to Count I and V of this Amended Complaint, for Counts II-IV, as detailed below, Plaintiffs also seek to certify subclasses consisting of owners and lessees within the States of Illinois, Massachusetts, and New Jersey of the foregoing vehicles.
 - 38. Although the exact number of class or subclass members is presently unknown,

Plaintiffs are informed and believe and thereon allege that the class as well as the subclasses will number in the thousands of consumers, thereby making joinder impracticable.

- 39. Class certification is also appropriate because there are questions of fact and/or law that are common to the class members. Among these common questions of fact and/or law are:
 - a. Whether Defendant is responsible for injecting allegedly defective vehicles in to the United States' stream of commerce;
 - b. Whether the subject vehicles are defective, and, if so, the nature of the defect;
 - c. Whether Defendant's conduct violates the New Jersey Consumer Fraud Act, and/or the Illinois Consumer Fraud Act,;
 - d. Whether Defendant breached any duty imposed upon it by law;
 - e. Whether any warranties, expressed or implied, were breached in connection with the sale and/or distribution of the subject vehicles;
 - f. Whether class members are entitled to the relief sought, and if so, the proper scope of such relief, including, but not limited to the proper measure of damages.
- 40. Plaintiffs' claims are typical of the claims of the absent class members in that Plaintiffs, like all the absent class members, claim that they are either the owners or lessees of a Mercedes vehicle that is equipped with either an M272 or M273 engine that is defective. Plaintiffs are members of the class they seek to represent, and the claims they advances on their own behalf are identical to the claims asserted on behalf of the class.
- 41. Plaintiffs are adequate class representatives in that, as members of the class and as current owners of allegedly defective Mercedes vehicles equipped with the M272 or M273

engine, their interests are entirely aligned with those of the class. There are no individual conflicts that prevent Plaintiffs from adequately representing the class. Plaintiffs have also retained competent counsel experienced in class action litigation.

- 42. Class certification is proper because common questions of fact and law predominate over questions that may affect only individual members of the class or subclasses. The subject vehicles are manufactured on an assembly line setting, subject to a common design and manufacturing plan, such that evidence of a defect in the balance shaft or idle gears would be one that would predominate over the entire class membership, as would evidence of Defendant's course of action, knowledge of the alleged defect, and any alleged concealment thereof.
- 43. A class action presents a superior form of adjudication over individual litigation. The costs of litigating this action against a large and sophisticated defendant like Defendant in comparison to the recovery or relief sought would make individual litigation impracticable. In addition, forcing individual litigation would risk the result of inconsistent rulings with respect to Defendant's duties owed to the various vehicle owners and lessees.
- 44. A class action is manageable. The proposed class represents an identifiable community that can be readily identified, and the relief sought is one that can be overseen by the Court.

COUNT I

(BREACH OF EXPRESS WARRANTY – ON BEHALF OF NATIONWIDE CLASS)

- 45. Plaintiffs hereby incorporate by reference all of the allegations of this Second Amended Complaint with the same force and effect as if they had been fully restated herein.
- 46. Plaintiffs Suddreth, Dunton, and Ricca are owners of Mercedes model vehicles equipped with the M272 engine containing the defect in the balance shaft gear detailed herein.

- 47. Like all such automobiles, when sold, the Plaintiffs' vehicles were subject to an express factory warranty issued by Defendant, whose terms purported to provide coverage for repairs and defects for a period of the earlier of 4 years or 50,000 miles since the vehicles' inservice date to the vehicles' original and subsequent owners.
 - 48. Specifically, the Mercedes express warranty provides, in pertinent part, that:

 Mercedes-Benz USA, LLC (MBUSA) warrants to the original and each subsequent owner of a new Mercedes-Benz passenger car that any authorized Mercedes-Benz Center will make any repairs or replacements necessary, to correct defects in material or workmanship arising during the warranty period.

Exh. 8 hereto, at 13.

The Warranty documentation specifically states that Mercedes' "intention is to repair under warranty, without charge to you, anything that goes wrong with your car during the warranty period which is our fault." *Id.* at 17.

- 49. As detailed herein, Plaintiffs' and class members' vehicles were defective within the warranty coverage period because a defect within the balance shaft gear or idle shaft was present from the date of the vehicles' manufacture and the injury to the gears was occurring and was ongoing within the warranty period.
- 50. Defendant has breached the terms of this express warranty by failing to correct, at no charge to class members, the subject defect. Rather, within the warranty coverage period, Defendant routinely denies that any such defect exists, or that its "discovery" has taken place outside the period of warranty coverage, and has therefore refused to repair the class members' vehicles, as required under the terms of Defendants' express warranty.
- 51. To the extent that Mercedes has claimed and continues to claim that it is justified in refusing to remedy and/or repair the subject defect in certain vehicles because the defect has been "discovered" only after the durational period of warranty coverage has elapsed, that

practice amounts to an unconscionable business practice, rendering Mercedes' justification unenforceable, and as a result, Defendant is and should be ordered to remedy the defect under warranty.

52. Adhering to the durational period of the warranty is unconscionable because, interalia. Defendant knew when it sold the subject vehicles (backed with the express warranty) that the defects alleged herein existed and failed to disclose the same to the vehicle owners, or to exclude coverage for the same within the terms of the express warranty. By the time Plaintiffs' vehicles were sold, Mercedes had received widespread complaints about the defect, leading it to: initiate a secret internal defect tracking study about the incidence of the defect; implement full coverage for repair of affected vehicles in Germany; and to ultimately, beginning in September 2006, manufacture a redesigned balance shaft gear of conventional steel so as to remedy the defect that plagued the gears manufactured prior to that date, which were composed of sintered steel. Not only did Mercedes merely fail to disclose this defect, which was known to Mercedes. but it affirmatively misrepresented that Plaintiffs' vehicles were free of quality concerns, and that any prior reliability issues plaguing prior model years of Plaintiffs' vehicles had now been resolved with the launch of the 2006 model year. The nature of the defects are such that they were known to Defendant but were not and could not have been known to, or discovered by, class members upon reasonable inspection of the vehicles prior to their purchase. Defendant's superior knowledge about the quality of the vehicles, including its defects, as well as Defendant being the sole issuer of the express warranty covering the subject vehicles, gave Defendant a superior bargaining power with respect to class members in setting forth the terms of the warranty coverage.

- knew of the existence and prevalence of the defect to the balance shaft gears, was also unconscionable in light of Mercedes' public recognition that the average life cycle of most of its models was 7.5 years. (See Paragraph 33 supra and Ex. 6 hereto). Mercedes' owner's manual cautions drivers that the vehicles should not be driven if the "Check Engine" light becomes illuminated (Ex. 9 hereto at p. 395). This is precisely the manner in which the defect at issue exhibited itself in Plaintiffs' vehicles. The net result is that vehicles that Mercedes had acknowledged and publicly announced had an average life cycle among consumers of 7.5 years, were known to Mercedes to contain a defect that would make them fail and be rendered non-driveable well before this period of time. Only by concealing its knowledge and misrepresenting the actual reliability and quality attributes of the vehicles, was Mercedes able to get Plaintiffs and consumers at large to "agree" to a warranty coverage of 4 years or 50,000 miles.
- 54. The allegations of the Amended Complaint demonstrate that the durational limits of the warranty are unconscionable under N.J.S.A. 12A:2-302, where the manufacturer, as here, knowingly places the defective consumer product into the stream of commerce with knowledge that it will fail shortly after the warranty period expires. Section 12A:2-302, entitled "Unconscionable contract or clause" states in pertinent part:
 - (1) If the court as a matter of law finds the contract or any clause of the contract to have been unconscionable at the time it was made the court may refuse to enforce the contract, or it may enforce the remainder of the contract without the unconscionable clause, or it may so limit the application of any unconscionable clause as to avoid any unconscionable result.
 - (2) When it is claimed or appears to the court that the contract or any clause thereof may be unconscionable the parties shall be afforded a

- reasonable opportunity to present evidence as to its commercial setting, purpose and effect to aid the court in making the determination.
- 55. Thus, the warranty limits are unconscionable or, alternatively the facts raise a question of fact as to unconscionability.
- 56. As a proximate, foreseeable, and direct result of Defendant's breach of its express warranty, Plaintiffs and the class members have suffered legal and actual injury, including the expenditure of money damages to have their vehicles repaired and associated expenses, damages associated with the loss of use and enjoyment of the vehicle, and damages associated with the decreased value of the vehicle.

COUNT II

(VIOLATION OF NEW JERSEY CONSUMER FRAUD ACT—ON BEHALF OF A SUBCLASS OF OWNERS AND LESSEES IN NEW JERSEY)

- 57. Plaintiffs hereby incorporate by reference all of the allegations of this Amended Complaint with the same force and effect as if they had been fully restated herein.
- 58. Plaintiff Ricca brings this count of this Amended Complaint on behalf of a subclass comprised of New Jersey owners and lessees of the subject vehicles, i.e. a New Jersey subclass of the class alleged in Paragraph 36 *supra* to seek redress for Defendant's violations of the New Jersey Consumer Fraud Act, N.J.S.A. § 56:8-2.
- 59. Defendant's failure to disclose as well as its intentional and fraudulent omission from any of its advertising and sales materials or brochures of the subject vehicles' defects, as well Defendant's actual misrepresentation as to the reliability and quality concerns associated with Plaintiffs' vehicles, at a time when Defendant knew of the prevalence of the defect plaguing the balance shaft gears in Plaintiffs' vehicles, coupled with Mercedes' denial of warranty coverage for repairs required as a result of these defects that were known to it, but concealed

from the public and misrepresented by Mercedes, amount to an unconscionable commercial practice, deception, fraud, false pretense, or the knowing, concealment, suppression, omission, or misrepresentation of any material fact with intent that others rely upon such concealment, suppression or omission, in connection with the sale or advertisement of the subject vehicles, thereby violating N.J.S.A. §56:8-2.

- 60. Among other things, Defendant knew that the subject vehicles had a defect which would cause them to fail before their expected useful life, and intentionally concealed that information from class members, with the purpose of maximizing profit, thereby independently violating the New Jersey Consumer Fraud Act. Beyond that, Defendant affirmatively represented the quality and reliability attributes of the subject vehicles at a time when it knew (but did not disclose) the defect plaguing the balance shaft and idle gears in the M272 and M273 engines.
- ascertainable loss and/or injury as a result of Defendant's violations of the New Jersey Consumer Fraud Act. Plaintiff Ricca has had to expend significant money to cover the repair bills required as a result of the defects. Further, Plaintiff Ricca and all of the New Jersey subclass members have sustained a diminished value of their vehicles as a result of the subject defect because, once the defect is disclosed as is being done through the filing of this lawsuit, the resale value of the vehicle will be negatively impacted as a specific and predictable result of the subject defect. In addition, each of the New Jersey subclass members has further suffered an ascertainable loss or injury because none of them has received the benefit of their bargain in connection with their purchase or lease of the subject vehicle. Instead, each received a vehicle bearing a latent defect in its balance shaft or idle gears.

COUNT III

(VIOLATION OF ILLINOIS CONSUMER FRAUD ACT – ON BEHALF OF SUBCLASS OF ILLINOIS OWNERS AND LESSEES)

- 62. Plaintiffs hereby incorporate by reference all of the allegations of this Amended Complaint with the same force and effect as if they had been fully restated herein.
- 63. Plaintiff Suddreth brings this Count of this Amended Complaint on behalf of a subclass comprised of Illinois owners and lessees of the subject vehicles, i.e. an Illinois subclass of the class alleged in Paragraph 36 *supra* to seek redress for Defendant's violations of the Illinois Consumer Fraud Act, 815 ILCS, §505/1 et. seq.
- 64. Defendant's failure to disclose and its affirmative misrepresentation, as well as its intentional and fraudulent omission from any of its advertising and sales materials or brochures of the subject vehicles' defects, coupled with Defendant's denial of warranty coverage for repairs required as a result of these defects that were known to it, but concealed from the public, amount to an unconscionable commercial practice, deception, fraud, false pretense, or the knowing, concealment, suppression, or omission of any material fact with intent that others rely upon such concealment, suppression or omission, in connection with the sale or advertisement of the subject vehicles, thereby violating the Illinois Consumer Fraud Act.
- 65. Among other things, Defendant knew that the subject vehicles had a defect which would cause them to fail before their expected useful life, and intentionally concealed that information from class members, and made affirmative misrepresentations to the contrary, with the purpose of maximizing profit, thereby independently violating the Illinois Consumer Fraud Act.
- 66. Plaintiff Suddreth and the Illinois subclass members have suffered loss and/or injury as a result of Defendant's violations of the Illinois Consumer Fraud Act. Plaintiff

Suddreth has had to expend significant money to cover the repair bills required as a result of the defects. Further, Plaintiff Suddreth and all of the Illinois subclass members have sustained a diminished value of their vehicles as a result of the subject defect because, once the defect is disclosed as is being done through the filing of this lawsuit, the resale value of the vehicle will be negatively impacted as a specific and predictable result of the subject defect. In addition, each of the Illinois subclass members has suffered a loss or injury because none of them has received the benefit of their bargain in connection with their purchase or lease of the subject vehicle. Instead, each received a vehicle bearing a latent defect in its balance shaft or idle gears.

COUNT IV

(BREACH OF IMPLIED WARRANTY OF MERCHANTIBILITY— ON BEHALF OF ILLINOIS, MASSACHUSETTS, AND NEW JERSEY SUBCLASSES)

- 67. Plaintiffs hereby incorporate by reference all of the allegations of this Amended Complaint with the same force and effect as if they had been fully restated herein.
- 68. Plaintiff Greg Suddreth alleges a claim for breach of the implied warranty of merchantability on behalf of a class or subclass of Illinois owners and lessees of the subject vehicles. Plaintiff Paul Dunton alleges a claim for breach of the implied warranty of merchantability on behalf of a class or subclass of Massachusetts owners and lessees of the subject vehicles. Plaintiff Paul Ricca alleges a claim for breach of the implied warranty of merchantability on behalf of a class or subclass of New Jersey owners and lessees of the subject vehicles.
- 69. Defendant is a merchant with respect to the distribution, sale, and leasing of Mercedes automobiles in the United States. With respect to the sale or lease of Plaintiffs' automobiles, the Mercedes dealerships from which Plaintiffs purchased their respective vehicles were acting as agents of Defendant. They were selected by Defendant, and authorized by

Mercedes to represent themselves as Mercedes-authorized dealers. They were further authorized to offer Mercedes warranty coverage on the vehicles only subject to Defendant's authorization and criteria.

- 69. By operation of law, an implied warranty of merchantability from Defendant attached to each sale and lease of the subject vehicles warranting that the vehicles were of merchantable quality.
- 70. Because the subject vehicles contain a defect in their balance shaft or idle gears that causes them to be unduly prone to experience engine misfiring, having a "check engine light" condition, or to stop running, they are of unmerchantable quality, and Defendant has breached its implied warranty of merchantability.
- 71. The subject vehicles are not merchantable because, *inter alia*: they would not pass without objection in the trade under the contract description; they are not of fair average quality within the description; they are not fit for the ordinary uses for which such vehicles are used; and, they are not adequately labeled.
- 72. The presence of the defect to the balance shaft or idle gears of the M272 and M273 engines renders the vehicles unmerchantable despite the fact that the vehicles may still be driven for a period of years before the defect exhibits itself. This is because Mercedes has recognized that consumers of the subject vehicles have come to expect that the vehicles shall be operable for an average life cycle of 7.5 years—a fact that Mercedes' spokespersons have touted in the press. Yet, the defect in the subject vehicles causes the "Check Engine" light to illuminate, as it did in the case of Plaintiffs' vehicles, well before this 7.5 year period.

 Mercedes' warranty manuals caution that vehicles should not be driven if the "Check Engine" light is illuminated. Further, some states, such as Massachusetts where Plaintiff Dunton's

vehicle was registered, will not permit the vehicle to pass inspection or be re-registered if its "Check Engine" light is illuminated. The net result is that the defect causes the vehicles to not be driveable for the commercially recognized period of time that Mercedes and the public have come to reasonable expect.

73. As a proximate and foreseeable result of this breach, Plaintiffs and the members of the subclasses have been injured by being forced to operate unmerchantable vehicles that did not correspond to the benefits of the subclass members' bargains.

COUNT V

(UNJUST ENRICHMENT—ON BEHALF OF NATIONWIDE CLASS)

- 74. Plaintiffs hereby incorporate by reference each and every allegation of this Amended Complaint with the same force and effect as if it had been fully restated herein.
- 75. Plaintiffs and the class members are each owners of Mercedes automobiles whose engines are defective in the manner detailed herein.
- 76. By purchasing a Mercedes branded automobile, Plaintiffs and the class members conveyed monetary as well as intangible benefits on Defendant, and Defendant appreciated and was enriched by those benefits.
- 77. As a result of Defendant's unjust and inequitable conduct alleged herein, including its distribution of defective automobiles into the United States' stream of commerce, as well as its failure to properly remedy those defects, it would be unjust and inequitable for Defendant to be permitted to retain these benefits.
- 78. Plaintiffs and class members are, therefore, entitled to and hereby pray for a judgment of restitution, ordering Defendant to disgorge its ill-gotten gains to the class members.

PRAYER FOR RELIEF

WHEREFORE, Plaintiffs and the class and subclass members pray for judgment against Defendant as follows:

- a) That the Court determine that this action may be litigated as a class action, and that
 Plaintiffs and their counsel be appointed class representative and class counsel,
 respectively;
- b) That the Court enter judgment against Defendant and in favor of Plaintiffs, the class and the subclasses on all counts;
- c) That Defendant be required by this Court's Order to create a common fund to remedy the defects alleged herein, and to compensate all members of the class and subclasses for their damages and injuries, as well as to compensate Plaintiffs' counsel for their attorneys' fees and cost of suit; and, that Defendant be ordered to bear the cost of notice the absent class members, as well as of the administration of this common fund;
- d) That damages and/or restitution or disgorgement be awarded to each Plaintiff and class or subclass member according to proof;
- e) That the Court award Plaintiffs and the members of the class and subclasses punitive damages assessed against Defendant;
- f) That Plaintiff and the class members be awarded all such other relief as this Court deems just and proper.

Plaintiffs request a jury trial on all counts so triable.

Dated this 29th day of November, 2011.

Respectfully submitted,

KANTROWITZ, GOLDHAMER & GRAIFMAN, P.C.

Gary S. Graifman 210 Summit Avenue Montvale, NJ 07645 Tel | (201) 391-7000 Fax | (201) 307-1086 Attorneys for Plaintiffs

Additional Plaintiff's Counsel (pro hac vice application pending):

Roy A. Katriel, Esq.

THE KATRIEL LAW FIRM

1101 30th Street, NW Suite 500

Washington, DC 20007

Telephone: (202) 625-4342 Facsimile: (202) 330-5593

EXHIBIT 1

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 26 of 51 PageID: 26

EXHIBIT 1

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 27 of 51 PageID: 27

BenzWorld.org is the premier Mercedes-Benz Forum on the internet. Registered Users do not see the above ads. 11-01-2009, 12:10 PM #1 (permalink) Has anyone ever had to replace their balance shaft? BenzWorld Junior Member I just picked my car up last week from the dealer, they had it all week ('06 C230 31,00 miles still under warranty) Date registered: Jul 2009 Vehicle: 2006: C230 Sport Location: Hawaii Poats (21 Is this common? I have searched and searched but it seems like it only happens to other models, not so much the 2.5L in the C230. 11-08-2009, 10:39 AM #2 (permalink) Achped BenzWorld Junior Member SO uhh, is that a no? pate registeredi 101 2009 Vehicles 2006 C230 Sport Locationi Hawaii 11-19-2009, 06:34 PM #3 (permalink) MBtechzyuz BenzWorld Member Hi there, I am actually a Mercedes-benz technician in North Carolina. To answer your question, this is not a very common problem, it mostly only affects the earlier 272 and 273 motors, which are the newer generation of v6 and v8 engines. Due to what I assume to be a problem with the manufacturer of the balance shafts, the gear on the end of the balance shaft actually wears down, making the gear smaller and causing the right side camshafts to be very Date registered: Nov 2009 Posts: 92 slightly out of time. This causes the check engine light to turn on. As a side note, the 273 motors do not have a balance shaft, they just have an idler gear that the timing chain rides on. I hope this helps. 🕏 11-21-2009, 07:09 AM #4 (permalink) Thats exactly what happened to mine. The CEL came on for both cams being out of time. When they tore the motor BenzWorld Junior Member apart it turned out that the balance shaft actually was worn causing it. Date registered: Jul 2009 Venicle: 2006 C230 Sport Location: Hawali Hopefully this won't happen again? Posts 21 11-22-2009, 07:55 AM #5 (permalink) it shouldn't, the new balance shaft they put in should not wear. The gear on the new shaft should be properly BenzWorld/Member hardened so I don't think you will need to worry about it. Last edited by MBtech2009; 11-23-2009 at 04:09 PM. Date registered: Nov 2009 Posts: 92 11-22-2009, 08:06 AM #6 (permalink) Quote: Moderator Originally Posted by MBtech2009 > Hi there, I am actually a Mercedes-benz technician in North Carolina. To answer your question, this is not a very common problem, it mostly only affects the earlier 272 and 273 motors, which are the newer generation of v6 and v8 engines. Due to what I assume to be a problem with the manufacturer of the balance shafts, the gear on Date registered: May 2007 Vehicle: 9320 (W220) and the end of the balance shaft actually wears down, making the gear smaller and causing the right side camshafts to be very slightly out of time. This causes the check engine light to turn on. As a side note, the 273 motors do not have a balance shaft, they just have an idler gear that the timing chain rides on. I hope this helps. 🥹 Location: Zhenzhou, Henan, China. He is correct and the 272 was about the worst for this problem but this is the first time I have heard of it on a C Posts: 17,332 Class. **餐**性的成分

ERIC.

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 28 of 51 PageID: 28

11-22-2009, 01:02 PM	#Z (permalink)
20066230Mike Benzworld Junior Member	Yup, I had the same problem.
Date registered: Nov 2008	But the dealer said they replaced the bearing, not the shaft.
Location, Boca Raton, FL Roses 10	So, I'm concerned it may show up again.
	Is the problem the shaft or the bearing?
An and a state of the state of	Thanks, I have about 2500 miles left on the warranty.
l. li1-23-2009, 04:12 PM	#8 (permalink)
MEtech 2009 Benzworld: Member	i think the dealer probably just wasn't clear with what they said. I am pretty sure that there isn't a replaceable bearing for the balance shaft, i think the bearing is actually made into the engine block, but I am not sure. I would be very surprised if they did something other than the balance shaft or intermediate gear (if you have a v8)
Date registered: Nov 2009 Poets: (92)	
1 1	
1 11-24-2009, 03:49 PM	#9 (permalink)
Strictiv4Roosting BenzWorld Member	im a ill worried how do i know if i participate i have an 07 benz but could of been made in 06 anyone know? ill go check the production date on the door
Date/registered/Mar 2009	07 c230
Posta; 60	
	#10 (permalink)
Banzworld Mamber ¥	or after the clean point for the engines that have the updated balance shaft.
Date registered: Nov 2009 Posts (92	AN SECURIOR SERVICE - OF DESCRIPTION OF THE SECURIOR OF A SECURIOR SERVICE AS A SECURIOR SECU
Pate registeretj: Nov 2009 Pošta: 92	
Poeta (92	novice needs balance shaft help
Folia (92	novice needs balance shaft help love my M8 but am a real novice about anything automotive. CEL went on two days ago, brought it into M8 and they told me that I needed to replace my balance shaft for a 06 E350 with 90k miles on it. Is this a common problem? I am being told it will take 3 days and \$4,000 to fix this which seems unbelievable when I have never had an issue with the car before.
vouncturkualis "Panzworld Newble Date registered: Dec 2009 Rosts: 2	love my MB but am a real novice about anything automotive. CEL went on two days ago, brought it into MB and they told me that I needed to replace my balance shaft for a 06 E350 with 90k miles on it. Is this a common problem? I am being told it will take 3 days and \$4,000 to fix this which seems unbelievable when I have never had an issue with the car before.
youngturkualg Benzworld Newble Date registered: Dec. 2009 Posts: 2!	love my MB but am a real novice about anything automotive. CEL went on two days ago, brought it into MB and they told me that I needed to replace my balance shaft for a 06 E350 with 90k miles on it. Is this a common problem? I am being told it will take 3 days and \$4,000 to fix this which seems unbelievable when I have never had an issue with the car before.
Youngturkualg BanzWorld Nawble Date registered: Dec 2009 Posts: 21	love my MB but am a real novice about anything automotive. CEL went on two days ago, brought it into MB and they told me that I needed to replace my balance shaft for a 06 E350 with 90k miles on it. Is this a common problem? I am being told it will take 3 days and \$4,000 to fix this which seems unbelievable when I have never had an issue with the car before. #13 (permalink) Unfortunately yes on your engine the balance shaft was a problem.
youndturkuald "Benzworld Newble Date registered: Dec 2009 Posts: 2! 112-05-2009, 07:14 AM eHe242340 Moderatol .x	love my MB but am a real novice about anything automotive. CEL went on two days ago, brought it into MB and they told me that I needed to replace my balance shaft for a 06 E350 with 90k miles on it. Is this a common problem? I am being told it will take 3 days and \$4,000 to fix this which seems unbelievable when I have never had an issue with the car before.
Voungturkualig Banzworld Nawble Date registered: Dec. 2009 Rosts: 2 112-05-2009, 07:14 AM elle242340 Mgderatol ** Date=registered: May 2007 Veltcie: \$320 (W220) and	love my MB but am a real novice about anything automotive. CEL went on two days ago, brought it into MB and they told me that I needed to replace my balance shaft for a 06 E350 with 90k miles on it. Is this a common problem? I am being told it will take 3 days and \$4,000 to fix this which seems unbelievable when I have never had an issue with the car before. #13 (permalink) Unfortunately yes on your engine the balance shaft was a problem.
Voungturkualig Benzworld Newble Date registered: Dec 2009 Rosts: 21 112-05-2009, 07:14 AM elie242340 Moderator	love my MB but am a real novice about anything automotive. CEL went on two days ago, brought it into MB and they told me that I needed to replace my balance shaft for a 06 E350 with 90k miles on it. Is this a common problem? I am being told it will take 3 days and \$4,000 to fix this which seems unbelievable when I have never had an issue with the car before. #13 (permalink) Unfortunately yes on your engine the balance shaft was a problem. ERIC.

 $\# \underline{14}$ (permalink)

12-05-2009, 03:40 PM

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 29 of 51 PageID: 29

MBtech2009 Yep, there is nothing you could have done or not done, the gear on your balance shaft has worn down and BenzWorld Member now your entire engine will have to be removed and disassembled in order to replace it, so \$4000 sounds about right. Iam not sure how car manufacturers decide when to do a recall on a part, but to me it seems like all of these cars with falling balance shafts should be covered by mercedes-benz. I am sure there is some Date registered: Nov 2009 Posts: 92 kind of person at mbusa that calculates how much it would cost to recall all of these cars with the faulty balance shafts, and how many of them are going to make it out of warranty and decides whether or not to do a recall. I would probably write a letter to MBUSA and let them know that you are disappointed that they would let so many cars go out of warranty with this problem, and maybe they will do something about it in the future. If you do get it replaced at the dealership, make sure to save your receipt, because if they do . . . come out with a recall for this you will be able to get your money reimbursed to you from mbusa. Last edited by MBtech2009: 12-05-2009 at 03:48 PM. 12-05-2009, 05:06 PM #15 (permalink) ouncturkuale thank you BenzWorld Newble a big thank you to you guys for taking the time to reach out and answer me, I greatly appreciate it Date registered: Dec 2009 12-05-2009, 07:33 PM #16 (permalink) Quote: BenzWorld Eilte Originally Posted by MBtach20D9 >
Yep, there is nothing you could have done or not done, the gear on your balance shaft has worn down and now your entire engine will have to be removed and disassembled in order to replace it, so \$4000 sounds about right. Jam not sure how car manufacturers decide when to do a recall on a park, but to me it seems like all of these cars with failing balance shafts should be covered by mercedes-benz. I am sure there is some kind of person at mouse that calculates how much it would cost to recall all of these cars with the faulty balance shafts, and how many of them are poing to make it out of warranty and decides whether or not to do a recall. I would probably write a letter to MBUSA and let them know that you are disappointed that they would let so many cars go out of warranty with this problem, and maybe they will do something about it in the future. If you do get it replaced at the dealership, make sure to save your receipt, because if they do come out with a recall for this you will be able to get your money reimbursed to you from mbusa. Originally Posted by MBtach2009 > Date registered: Dec 2004 Vähigle: 2002 C240 (current), 2001 ML320 (förmer) Location: Birmingham, AL Posts: 1,864 The key word to use when trying to get this paid for by MBZ is "goodwill". They don't like to admit that they . . have defective parts, but they will sometimes help customers with expensive repairs, especially when the customer know it's a common problem and they are not long out of the warranty period. - RODNEY 12-06-2009, 12:21 AM #17 (permalink) eric242340 Moderator Quote: Will Const Originally Posted by rudency : The key word to use when trying to get this paid for by MBZ is "goodwill". They don't like to admit that they have defective parts, but they will sometimes help customers with expensive repairs, especially when Date registered: May 2007 Vehicle: \$320 (W220) and Zotye 1:3 the customer know it's a common problem and they are not long out of the warranty period. Very good point and he should seriously think about your point. Location: Zhenzhou, Henan, Posts: 17:332 112-06-2009, 07:38 AM #<u>18</u> (<u>permalink</u>) MBtech2009 BenzWond Member I doubt that the dealer would goodwill this repair, seeing as you have 90k miles and it's an 06, maybe If it was just out of warranty, like 52k miles. Note: in the USA all of the dealerships, except one in manhattan, are privately owned, they are not actually part of MBUSA, but I would say it is worth a try, especially if you have been a loyal customer to this dealership and have had all your services done there. Date registered: Nov 2009 Posts: 92 12-12-2009, 05:12 AM #19 (permalink)

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 30 of 51 PageID: 30

ierk chicken Benzworld Extremist Date registered Jun 2008 Venicle 2000, w203 c200k (Yes it's a w203 mom German) Logation Germany Rosts 1,1052 I12-14-2009, 07:0-1 AM Strictiv/Boosting Benzworld Member Date registered; Mar 2009 Rosts 160	#20 (permalink) I think forming a pact and having the same people all together in this forum to correct the problem of the balance shaft they have to recall all those cars and fix them before the problem gets worse.
Date registered May 2007 Vehicle S320 (W220) and Zove 13 Location, Zhenzhou, Henan, China Posts 17,335	Quote: Originally Posted by Strictly 4B oosting : Originally Posted by Strictly 4B oosting : I think forming a pact and be ing the same people all together in this forum to correct the problem of the balance shaft they have to recall all those cers and fix them before the problem gets worse. Nice to see you are getting the picture.
Date registered Dec 2009 Rosts 6 12-22-2009, 05:51 PM MBtach2009 Benz World Member:	The dealer told me I had the same problem with the balance shaft, and told me it was a common problem, they would fix it for \$4000 and mercedes would kick in \$2000 because it is a common problem. They also told me it was not a safety issue or performance issue and not to worry about it. Well the State of Massachusetts will not give me an inspection sticker so I have to worry about it. I just called Mercedes Benz USA where the lady I spoke with told me it is not a common problem and everyone on this website is a liar. They told me if it were a common problem it would have been recalled. I will continue to fight with them and potential start a class action lawsuit if enough people have had the same problems. I will keep you all informed of my progress. #23 (permalink) I guess it all depends on your definition of common is. I've seen some campaigns that mercedes has done that only covered 14 cars. I just think that they are studying this problem and trying to figure out the best way to deal with it. I am sure this problem is happening all over the world and something is going to have to be done about it.
Date registered: Nov 2009 Postal 92 12-22-2009, 07:57 PM Sric242340 Moderator: T Date registered: May 2007 Vehicle: S320 (W220) and	I will give you a little known thing here, when we test the car using DAS and find a fault code leading to the two exhaust cams being fully retarded if we click on the fault code to find out what to do next it tells us to check for balance shaft wear. This means that MB know of this problem and have done for a long time.

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 31 of 51 PageID: 31

Zotye 1,3 Location: Zhenzhou, Henan,

China

Posts: 17,333

. 12-22-2009, 10:05 PM

#25 (permalink)

BenzWorld Extremist

The best way to deal with it is have the owners pay because they know most of them will. Hell, you even see people on this forum flaunting their repair or maintenance bills at the dealers as a sign of status or privilege.

Date registeredi Jun 2008 Vehicle: 2000 w203 c200k (Yes, Jus a w203 from Germany) Location: Germany Posts: 1,052

12-23-2009, 03:48 PM

#26 (permalink)

<u>MBtech2009</u> BenzWorld Member

Date registered: Nov 2009 Posts: 92

Mercedes has had a bulletin about this issue since august 23 2007. They have made 10 revisions to the bulletin over the past 2 years, which mainly consist of adding more models that the bulletin relates to and revising the content of the bulletin slightly. So they have known about this since at least then, and probably earlier since I am sure they have to research the Issue before they issue the bulletin. I can say for a fact that my dealership has done 4 balance shaft replacements in the past month. I know that some dealers are doing way more than that a month. So lets say 4 per month times roughly 300 dealers, that's roughly 1200 a month, and in my opinion that's alot. I think that so far all of the ones that we have done were either under warranty or our dealer covered it under goodwill. I really hope that mercedes decides to make some kind of extended warranty on this part for the vehicles in the affected range.

112-24-2009, 08:48 AM

#27 (permalink)

<u>letk cilicken</u> BenzWorld Extremist

Not without a class action threat, like with the v8's that had the problem oil passages.

Date registered: Jun 2008 Vehicle: 2000 w203 c200k (Yes, it's a:w203 from Germany) Location Germany Posts: 1,052

12-24-2009, 09:40 AM

#<u>28</u> (<u>permalink</u>)

rib190a Moderator

I just finally got around to reading this thread. I'm hoping my '07 is in the clear but it's got a 9/06 production date. Besides the check engine light what other symptoms would you see if your engine has this problem? Noisy, rough rough running, poor mileage?

Date registered: Apr 2006 Vehicle: 98 C230 '07 C230 Sport 86 2,3-16 Location: Delaware Beach Posts: 3,589

12-24-2009, 08:43 PM

#29 (permalink)

BenzWorld Member

Date registered: Feb 2008 Vehicle: 2006 C230 Sport, 96 C220 , 06 Ford F150Sc, 04 Honda Pliot EXL

I have an 06 C230 with a 09-05 built date, it now has 44K miles, and is now driven only 6K miles/year, I decided not to worry about this balance shaft albatross, I will deal with it when it happens. I have finally decided that these new Mercedes Benz have an ownership experience more in the realm of owning an Alfa Romeo, nice exclusive good cars, but a little bit temperamental, and definetely will never earn the mlleage badge Mercedes use to issue.

My old 96 ,C220 is now only 15K miles away from the badge.

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 32 of 51 PageID: 32

Location: Rancho Belago , California Posts: 51

12-24-2009, 09:49 PM

#30 (permalink)

<u>lerk chickén</u> Benzyprid Extremist

Date registered: Jun 2008 Vehicler: 2000 w203 c200k (Yes: Its a.w203 from Germany) Ligation: Germany Posts: 1,052

I was showing this to my gf and her family, who recently started dumping their MB's after some 40 years of ownership. We're all glad that we "accidentally" got an m111 c-klasse, rather than going for a slightly newer, m271 disaster. Man, what is up with these engines? Cylinder heads, balance shafts, timing sets, cam sensors, cps sensors...etc. Is it that the bulk of people with Benzes drive them infrequently, so they ride out the warranty before they get up to mileage where things prematurely fall? Even out on this market, it was easy to find low-mileage MB's, while damn near impossible to find low-mileage Audis, just like in the US. Hell, I used to do 40k a year on mine. My 2000 C200k was purchased at less than 40k miles a year and a half ago.

112-25-2009, 06:19 PM

#31 (permalink)

F150SC BenzWorld Member

Quote:

Dete registered: Feb: 2008 Vehicle: 2006 C230 Sport, 96 C220: 06 Ford: P150Sc. 04 Honda: Rilor EXL Location: Rancho Belago; Çaliforna Rosts: 61 Originally Posted by jerk_chicken >

I was showing this to my of and her family, who recently started dumping their MB's after some 40 years of ownership. We're all glad that we "accidentally" got an m111 c-klasse, rather than going for a slightly newer, m271 disaster. Man, what is up with these engines? Cylinder heads, belance shafts, timing sets, cam sensors, cps sensors...etc. Is it that the bulk of people with Benzes drive them infrequently, so they ride out the warranty before they get up to mileage where things prematurely fall? Even out on this market, it was easy to find low-mileage MB's, while damn near impossible to find low-mileage Audis, just like in the US. Hell, I used to do 40k a year on mine. My 2000 G200k was purchased at less than 40k miles a year and a half ago.

I now drive my 2006 C230 infrequently, but my extended warranty ends on 12-2010. I now resign myself to balance shaft repair sometime, in the next few years. No matter how well they road tested the new W204, a part supplier will always screw things up, I predict a new mechanical issue will show up on the new W204 as well, just as they did on our W203. Anyway I still like these cars.

12-25-2009, 10:54 PM

#32 (permalink)

<u>lerk chicken</u> BenzWorld Extremist

Date registered: Jun 2008 Vehicle: 2000 w203: c200k (Yes. It's a w203 from Germany) Location: Germany Poets: 1,052 parts suppliers always screw up, but it appears to be at a very incidence for parts that are typically considered lifetime. Couple this with the leaking cam sensors and the m271 head problems, and this engine is truly a disaster. Regardless of it being a parts supplier, the end consumer does not deal with them-they deal with Mercedes, and typically, when parts fall, it's due to bean counting and lack of oversight from the company requesting the parts, in addition to using ones that are inappropriate for an application.

Just because you're resigned to balance shaft repair doesn't mean it's right, and it's typical behavior like that which has allowed mercedes to slip so far down the shitter- they know they will always have customers like you, whom they don't have to try at all to get business from.

12-25-2009, 11:16 PM

#33 (permalink)

<u>F150SC</u> BenzWorld Mambel

١

Date registeredi Feb 2008 Vehicle 2006 C230 Sport, 96 C220, 06 Ford F150Sc, 04 Honda Rigi: #XI. Location: Rancho Belago, Celifornia Posts: 51

Quote:

Originally Posted by jerk_chicken >

parts suppliers always screw up, but it appears to be at a very incidence for parts that are typically considered lifetime. Couple this with the leaking cam sensors and the m271 head problems, and this engine is truly a disaster. Regardless of it being a parts supplier, the end consumer does not deal with them—they deal with Mercades, and typically, when parts fall, it's due to be an counting and lack of oversight from the company requesting the parts, in addition to using ones that are inappropriate for an application.

Just because you're resigned to balance shaft repair doesn't mean it's right, and it's typical behavior like that which has allowed mercedes to slip so far down the shitter- they know they will always have customers like you, whom they don't have to try at all to get business from.

So far I have been lucky, no problems with my Mercedes Benz, all three of them, but I gave up in getting any good expectations from this company, I always keep two cars just for myself, the other brand is Ford, similar quality levels, but 50% cheaper in price, next car is a Mustang GT V8

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 33 of 51 PageID: 33

Walk Saide House	
112-27-2009, 05:50 PM	# <u>34 (permalink)</u>
imlyrick BenzWörld Junior Member * Date (egistered: Dec 2009	Do the M111 or M112 engines suffer from this Balance Shaft Problem?? I am looking to buy one of these: "02 C230 K Coupe - assumed to be an M111 engine "03 C230 K Coupe - assumed to be an M111 engine "04 C320 Coupe - assumed to be an M112 engine
Poste: 26	Help me avoid making a costly mistake - Thanks
12-27-2009, 08:00 PM	/ <u>35</u> (permalink) :
er io242340 Moderator	Quote:
Date registered: May 2007 Vehicle: 9320 (W220) and	Originally Posted by jmlynick > Do the M111 or M112 engines suffer from this Balance Shaft Problem?? I am looking to buy one of these: "02 C230 K Coupe - assumed to be an M111 engine "03 C230 K Coupe - assumed to be an M111 engine "04 C320 Coupe - assumed to be an M112 engine
Zorye 1.3 Lodation: Zhenzhou, Henan, Ghina	Help me avoid making a costly mistake - Thanks
Rosts: 17,333	As far as I know it is only the 271/272 engines, but I may be wrong. ERIC.
	EKIC.
112-28-2009, 01:20 AM	# <u>36</u> (<u>permalink</u>)
ierk-chloken Benzworld Extremist	How bad of a job is it for one to do on their own? Cost of parts?
Date registered: Jun 2008 Veriicle 2000 w203 c200k (Yes) It's a w203 from Germany) Location: Germany Rosts: 1,052	
Lange 2010 of the second	
.02-04-2010, 02:25 PM	#37 (permalink)
Benzworld Newbie	Same issue with my 06 ML 350 Was just told by my mechanic I have this issue. I actually had it in to the dealer a year ago with a cam shaft sensor
Date régistered: Feb 2009 Rosts: 4:	issue and they did not replace this. I am looking for others to look into a class action lawsuit. My current mechanic provided me all the bulletins that have been issued on this at well. Contact me at qreg@suddreth.com
. l02-05-2010, 05:48 AM	#38 (permalink)
peuldunton BenzWorld Junior Member	Quote:
Dete registered: Dec 2009 Posta: 6	Originally Posted by suds4333 : Was just told by my mechanic I have this issue. I actually had it in to the dealer a year ago with a cam shaft sensor issue and they did not replace this. I am looking for others to look into a class action lawsuit. My current mechanic provided me all the bulletins that have been issued on this at well. Contact me at greg@suddreth.com
	Thats exactly what happened to me with the cam shaft sensor 8 months before balance shaft. My car went in to shop for balance shaft in December, got it back a week later and CEL came on again. Has now been back in shop for the last 3 weeks, they apparently screwed something up doing the balance shaft and are now doing it all over again.
l lo2-08-2010, 09:24 PM	#39 (permalink)
suds4333 BeinzWorld: Newble	All right folks, it is time to unite. After reading this board and several others and talking to my mechanic, it looks like there is a significant issue with the balance shaft. My MB dealer, the first time I had it in, did a short term fix to get me off their butts and out of warranty by changing the cam shaft sensors. By here I am a couple round of new

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 34 of 51 PageID: 34

Date registered: Feb 2009 sensors and an honest mechanic later and the issue is the balance shaft and the timing. I can be reached at Posts: 4 greg@suddreth.com or 815-557-5731. Most of us have probably spent 1000's of dollars on this and enough is enough. 02-13-2010, 08:02 AM #40 (permalink) <u>Fomilis</u> BenzWorld Newble There is no temporary fix for this, even by replacing all cam solenods and clearing the faults in the ME the check engine light will return within a day. Replacing cam adjustment solenoids is a extremely common repair, they go bad all the time. I assume over time MB will probably not release a recall, but extend the warrenty like they did with Date registered: Mar 2008 220 Instrument clusters and 211 SBC pumps. That being said though, everyone that runs into this problem should ask for goodwill help since this is a almost guaranteed problem with 06 and 07 cars before they hit 100k, 02-13-2010, 08:10 AM #41 (permalink) erle242340 Moderator Quote: Originally Posted by Epmills **SECOND** There is no temporary fix for this, even by replacing all cam solenous and clearing the faults in the ME the check engine light will return within a day. Replacing cam adjustment soleholds is a extremely common repair, they go bad all the time, I assume over time MB will probably not release a recall, but extend the warrenty like they did with 220 instrument clusters and 211 SBC pumps. That being said though; everyone that runs into this problem Date registered: May 2007 Vehicle: 6320 (W220) and Zotye 1,3 should ask for goodwill help since this is a almost guaranteed problem with 06 and 07 cars before they hit 100k. ocation: Zhenzhou, Henan, The most accurate and honest reply I have read so far China Posts: 17,383 ERIC. 02-13-2010, 01:40 PM #42 (permalink) Bomille Quote: Benzworld Newble Originally Posted by eric242340 > Date registered: Mar 2008 The most accurate and honest reply I have read so far Posts: 3 Haha why thank you, if you ever stop by the states and Visit the STL area let me know and i'll fix $x_{000-000}$ right. 02-27-2010, 07:14 AM #43 (permalink) <u>smitch</u> Premium Member Quote: Originally Posted by F150SC > I have an 06 C230 with a 09-05 built date, it now has 44K miles, and is now driven only 6K miles/year. I decided not to worry about this <u>bilance</u> shalt albatross, I will deal with it when it happens. I have Anally decided that these new Mercedes Benz have an ownership experience more in the realm of owning an Alfa Date régistered; Apr 2005 Venicle: 2002 ML320, 2006 ML350 SOLD, 2010 F150 Crew Romeo, rilçə exclusive good cars, but a little bit temperamental , and definetely will never earn the mileage badge Mercedes use to Issue. My old 96 ,C220 is now only 15K miles away from the badge. Cab. Location: Ala-Tenn Tempermental would describe a vehicle that needs to be petted and meticulously maintained. This is an outright Posts: 8,518 manufacturing flaw. In itself, it lets down the consumer and creates an atmosphere of arrogance on MB's part if they look away while whistling past the graveyard on this issue. While my own research hasn't turned up the probability that ALL engines that fall into the serial # range will have a balance shaft failure, it does seem likely that with most 272's it's not a question of if, but when. When I purchased my ML350, I was immediately impressed with the quality that was miles above their predecessor, the W163. As with any thrill of ownership, Mercedes manages to snuff it out with their inability to step up to the plate and do right by their customers and fix these before possible permanent damage is done. 03-09-2010, 03:01 AM #44 (permalink) samm Mbalance shaft replacement!! Urgent help needed! BenzWorld Member thought I'd put a little info here for those who cant afford to let the dealer take 4500 to do this job. I will do a full

write up of how I went about it in due course...

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 35 of 51 PageID: 35

Date registeredi Jan 2004 Vehicle: Mercedes 300E 1991 Location: London England Posts: 101

But now I need some urgent help please. I need someone who has the WIS software to please tell me how to set the position of the camshafts as the timing was messed up due to the massively worn out balance shaft.

Its a 2006 clk350 with 272.960 engine. I have the alldata settings but they appear to be wrong as the camshafts are completely wrongly set (wrong valves will be opening contrary to the firing order 1,4,3,6,2,5) if I go with their setting.

I really would appreciate the help and I will be helping others with my write up as well.

Thank you very much in advance,

.03-09-2010, 07:34 PM

Quote:

<u>F1503G</u> BanzWorld Member

Pāte registered: Feb 2008 Vehicle 2006 (230 Sport, 96 G220: 06 Ford F150Sc, 04 Honda Pilot EXL Location: Rancho Belago , Gelifornia Pōels: 51 Originally Posted by cmitch >

Tempermental would describe a vehicle that needs to be petted and meticulously maintained. This is an outright manufacturing flaw: In Itself, it lets down the consumer and creates an atmosphere of arrogance on MB's part if they look away while whistling past the graveyard on this issue. While my own research hasn't turned up the probability that ALL quilles that fall into the serial # range will have a balance shaft fallure, it does seem likely that with most 272's it's not a question of if, but when.

that with most 272's it's not a question of if, but when,
When I purchased my ML350, I was immediately impressed with the quality that was miles above their
predecessor, the W163, As with any thrill of ownership, Mercedes manages to soulf it out with their inability to
step up to the plate and do right by their customers and fix these before possible permanent damage is done.

To be fair to Mercedes Benz, all newer cars are designed to be very reliable the first 5 years (MBZ included), however after 5 years or 50K miles all the electronics and other stuff the like balance shafts and variable valve etc, will periodically fail. The most common survivors today are the old W123, I see lots of them, they were robust and simple. All new cars are just too complex. Even Toyotas are unreliable.

03-11-2010, 03:22 PM

#46 (permalink)

#47 (permalink)

#45 (permalink)

BenzWorld Junior Member

Date regiatered: Apr 2009 Vehlole: Mercedes Benz C350 4Matic 2006

Location: Connecticut Rosis: 12 After reading this thread and looking at other references about the balance shaft issue on other forums, I've learned that my 06 C350's vin falls under the range of affected models.

I'm glad I still have part of my warranty left, but it really has me worried about a looming \$4000 repair that could possibly happen after it runs out. Does anyone know how likely is it to happen? Is it something that regular maintenance will prevent or is just plain luck?

:03-12-2010, 05:59 AM

Quote:

aric242340 Moderator

Originally Posted by Jimgar >
After reading this thread and looking at other references about the balance shaft issue on other forums, I've learned that my 06 C350's vin falls under the range of affected models.

Date ragistered: May 2007 Vehicle \$320 (W220) and Zotye 1:3 Location Zhenzhou, Henan,

Location Zhenzhoù, Henan, China Posts: 17,333 I'm glad I still have part of my warranty left, but it really has me worried about a looming \$4000 repair that could possibly happen after it runs out. Does anyone know how likely is it to happen? Is it something that regular maintenance will prevent or is just plain luck?

From my experience thus far it seems to be just luck or the lack of. Sorry

03-14-2010, 01:05 PM

#48 (permalink)

mbtech101 BenzWorld Member Quote:

Date registered: Mar 2010 Posts: 51 Originally Posted by Achped >

Thats exactly what happened to mine. The CEL came on for both cams being out of time. When they tore the motor apart it turned out that the balance shaft actually was worn causing it.

Hopefully this won't happen again?

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 36 of 51 PageID: 36

	no it wont, the early balance shaft had different metals/material that failed, the new one is different
1. 03-14-2010, 01:07 PM	#40 (120 months)
mbtech101	#49 (permalink) Quote:
Benzworld Member	Originally Posted by effc242340 %
Date registered: Mar 2010 Posts: 51	From my experience thus far it seems to be just luck or the lack of. Sorry certain engine serial numbers are affected on the v6 and much more less likely on the v8. usually occurs around the
the company of the party	40k miles mark but seen it at 100k once
03-14-2010, 01:10 PM	#50 (permalink)
mbtesh101 Benzworld Member	Quote:
	Originally Posted by samm >
Date registered: Mar 2010 Posts: 51	Hey guys, thought I'd put a little into here for those who cant afford to let the dealer take 4500 to do this job. I will do a full write up of how I went about it in due course
	But now I need some urgent help please. I need someone who has the WIS software to please tell me how to set the position of the camphants as the timing was messed up due to the massively worn out balance shaft.
	Its a 2006 clk350 with 272,960 engine. I have the alidata settings but they appear to be wrong as the camshafts are completely wrongly set (wrong valves will be opening contrary to the firing order 1,4,3,6,2,5) if I go with their setting:
	I really would appreciate the help and I will be helping others with my write up as well.
	Thank you very much in advance,
	if the balance shaft was completely worn and u marked the cam to the chain it should be perfect to the new shaft, it doesn't jump timing when this happens. I can set the timing with my eyes closed on these, the exhaust cam gears have to locked before removal, did u do that?
	#51 (permalink)
mbrech101 /Behzworld Member *	if you beat on the $rac{car}{car}$ it will occur much sooner than driving like a grandma
Date registered: Mar 2010 Posts: 51	
04-23-2010, 12:39 PM KCWesg	# <u>52</u> (<u>permalink</u>)
RenzWorld Newble	balance shaft E-350
Date registered: Apr 2010 Postsi 2	I was just informed that my 2006 e-350 needs to get the balance shaft replaced. Unfortunately, I am out of warranty; if they would have caught this problem 3 weeks ago when i brought it in for service, my warranty would have covered it. Now I am soi. I need to know if there have been any recalls or problems with the E-350 balance shafts.
04-23-2010, 07:22 PM	# <u>53 (permalink</u>)
rudenev BenzWorld Elite ★	Three weeks? Ask the dealer if they can get MBZ to cover it under "good will".
	- RODNEY
Cave registered; Dec 2004 Vehicle: 2002 C240 (current), 2001 ML320 (former)	
Locationi Birmingham, AL Posts: 1,864	

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 37 of 51 PageID: 37

1 04-23-2010, 09:54 PM	#54 (permalink)
<u>evid242340</u> Möderatör	Quote:
Date registered: May 2007 Vehicle: \$320 (W220) and	Originally Posted by knwesq > I was just informed that my 2006 e-350 needs to get the balance shaft replaced. Unfortunately, I am out of warranty; If they would have caught this problem 3 weeks ago when I brought it in for service, my warranty would have covered it. Now I am soi, I need to know if there have been any recalls or problems with the E-350 balance shafts.
Zófye 1.3 Location: Zhenzhou, Henan, China	You should of had the cel on a few times before this happened, me thinks you are being cheated. 🗭
R05)8: 17,334	ERIC.
A STATE OF THE STA	
04-24-2010, 07 :08 PM	# <u>55</u> (<u>permalink</u>)
KGWest Benzworld Newbie Date registered; Apr 2010 Posts; 2	I was dismayed when the service guy told me that this will cost me about 5k and that he could not do anything for me; he told me straight out that I had to deal with MB directly. No good will at all. He also told my husband that the shaft could go bad due to: bad gas, type of oil and high temperatures!! I mean, I took the damn car to every single service required, never mistreated it (i considered it my baby) it was the dealer who changed the oil and it never overheated. I mean, do they think I am stupid or what? I cant believe that one of the strongest parts of an engine could just go bad due to gas, oil and overheating!! I need to know if there was any recalls on this or any concession of this problem by MB. Thanks everyone
94-27-2010, 04:48 PM	#FC (Normalina)
MB(ech2009	#56 (permalink)
BenzWorld Member Date registered: Nov 2009 Rosts, 92	First of all, I wouldn't call the balance shaft one of the strongest parts of the engine, but that really isn't important, the gear is the problem. Mercedes knows there is a problem with the gears on early 272 and 273 engines. The gears were not properly hardened from the manufacturer of the part and therefore the gear wears downover time. Mercedes should help you out with this, there is nothing you could have done to cause or prevent this so you should not feel like it is your fault at all.
	WEST Transport
61505C	#57 (permalink) Quote:
BenzWorld Member	Oulstoolly Doobled by Aspen at Books I.
Pate registered: feb 2008 Vehicle: 2006 C230 Sport, 96 C220; 06 Förd F150sc, 04 Honde Pllot EXL Location: Rancho Belago ,	Originally Posted by MBtech2009 > First of all, I wouldn't call the balance shaft one of the strongest parts of the engine, but that really isn't important, the gear is the problem. Mercelles & knows there is a problem with the gears on early 272 and 273 engines. The gears were not properly hardened from the manufacturer of the part and therefore the gear wears downover time. Mercedes should help you out with this, there is nothing you could have done to cause or prevent this so you should not feel like it is your fault at all.
Gallfornia Rosis: 51	I have an early 272 with 45K miles, most early 272's probably have close to 60K miles by now, so these are suppose to fail between 35K and 90K for 100% of all 272's. I already budgeted \$4,000 for this event between now and 90K miles, if it happens within the next 5 years, \$4,000 is worth the money to keep a well kept car running, beyond that , it depends.
04.70.2010-04.40	
04-29-2010, 04:10 AM	# <u>58</u> (<u>permalink</u>)
MBtech2009 BenzWorld Member * Date registered Nov 2009 Posts: 92	I don't think that this will happen to 100% of 272 or 273 engines. Mercedes knows the last engine number for the 272 and 273 engines that had the possibility of having the incorrectly hardened balance shaft. My guess is that the only reason that mercedes never issued a recall campaign for these early engines is that they don't know which ones have the incorrectly hardened balance shaft gear and which ones do. The only way to tell the part number of the balance shaft is to take the engine apart and look at it, and mercedes doesn't want to pay to take all of these engines apart if a large majority of them are not going to fall. Or it could be that they figure alot of them are going to make it out of warranty and that is what they care about, i'm really not sure. I just think that if they knew which ones were bad they would have fixed them instead of just coming out with a dtb, which originally came out in august of 2007.
1	
	# <u>59 (permalink)</u>

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 38 of 51 PageID: 38

F150SC Ouote: BenzWorld Member ¥. Originally Posted by MBtech2009 > I don't think that this will happen to 100% of 272 or 273 engines, Mercedes knows the last engine number for Date registered: Feb 2008 Vehicle: 2006 C230 Sport, 96 G220: 06 Ford F150Sc, 04 Honda Plot EXI; Location: Rancho Balago, the 272 and 273 engines that had the possibility of having the incorrectly hardened balance shaft. My guess is that the only reason that mercedes never lesued a recall campaign for these early engines is that they don't know which ones have the incorrectly hardened balance shaft geer and which ones do. The only way to tell the part number of the balance shaft is to take the engine apart and look at it, and marcades doesn't want to pay to take all of these engines apart if a large majority of them are not going to fall. Or it could be that they ligure alot of them are going to make it out of warranty and that is what they care about. I'm really not sure, I just frink Galifornia Posts: 51 that if they knew which ones were had they would have fixed them instead of just coming out with a dib, which originally came out in august of 2007, My Indy mechanics answer to the question of the possibility of a balance shaft gear failure is "Yes and No". I do believe in your theory that it is a random failure in quality, not a total across the board failure of those gears. 06-22-2010, 05:31 AM #60 (permalink) <u>þauldúritón</u> BenzWorld Jünlör Member Anyone experiencing similar problems with this engine please email your information to hmexecutive@yahoo.com she is trying to get a suit going. Date registered: Dec 2009 07-06-2010, 03:50 PM #61 (permalink) <u>Galene Reese</u> BenzWorld Newbie I am about to have a Gear on the balance shaft on my 2006 C240 replaced. The CEL stays on after servicing. Estimated at \$4000.00. Is this normal? I have 68,000 miles. Date registered: May 2009 Posts: 2 07-06-2010, 04:06 PM #62 (permalink) Galene Reese I am about to have a Gear on the balance shaft on my 2006 C240 replaced. The CEL BenzWorld Newble stays on after servicing. Estimated at \$4000.00. Is this normal? I have 68,000 miles. Date registered: May 2009 Posts: 2 #63 (permalink) 07-27-2010, 11:59 AM I have a 2006 ML350 with 56,000 miles at the dealer right now to replace the balance Benzworld Junior Member shaft. I've started a facebook page for owners who have had the same problems with that motor to get everyone together with this issue. Maybe a possible class action in Date registered: Jul 2010 the future?? Posts: 6 Join at Mercedes - Benz (Balance Shaft Problems) | Facebook Or on facebook, search Mercedes 4 - Benz (balance shaft problem) .07-27-2010, 04:08 PM #64 (permalink) Are you guys talking about Harmonic Balance Pulley? I am aware of the Harmonic BenzWorld Extremist Balance pulley problem on ML; however, I have not heard about the Harmonic Balance shaft problems. Date registered: Feb 2005 Vehicle: '07 C280, '04 C320, '98 ML320

Location: Nashua, NH

Case 2:10-cv-05130-DMC-JAD Document 28-1 Filed 12/01/11 Page 47 of 82 PageID: 567

Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 39 of 51 PageID: 39

Pošis (1,186	
☐ 08-16-2010, 06:20 PM	#65 (permalink)
sugs4388 BerizWorld Newble Date:registered: Feb 2009 Posts: 4	I am looking for someone with the Balance Shaft issue that is the original owner of their Mercedes. I have a class action attorney and he is looking for another person to be named in the class action case. Contact me at greg@suddreth.com or 815-557-5731

Case 2:10-cv-05130-DMC-JAD Document 28-1 Filed 12/01/11 Page 49 of 82 PageID: 569 Case 2:10-cv-05130-DMC -JAD Document 1 Filed 10/05/10 Page 40 of 51 PageID: 40

 Hom Buy Part o Fastlán o AllPartsExpres Special Too Shop Forur Resource o What's New o <u>DIY Article</u> o DIY Link o Good Shor o Featured Car

PeachParts Mercedes ShopForum > Technical Information and Support > ML.

User Name User Name

Remember Me?

Log in

🔐 GL, G-Wagen, R-Class, Unimog, Sprinter

ML350 3.5L Balance Shaft Failure

Calendar

Search

Register

ShopForum Gallery

FAQ

Password

Today's Posts



Page 1 of 2 1 2 > 47

Thread Tools C7 Display Modes C7

図 02-20-2010, 11:05 AM



Join Date: May 2000

Location: Location: Norcross, GA

Posts: 77

ML350 3.5L Balance Shaft Fallure

What a surprise!.. Wife's '06 ML350 had intermittent CEL. Last year, dealer replaced cam / timing position sensors. Problem continued to occur with CEL coming on even more frequently. NOW, they tell me that the Balance Shaft has a bad gear and it is deteriorating. 73K miles. Thank goodness for extended warranties. Finding from other web site threads and blogs that MB USA is not consistent with the treatment of customers... some customers are bearing the full cost of the repair while others are being offered "good will" discounts. Appears there had been a service bulliten out for 2 1/2 years on this problem with no sign that MBUSA is stepping up to cover a known fault, roughly 10 updates to the bulliten adding vehichles to the list.

Any other Shop Forum members experiencing this? Not exactly the kind of news one expects when you take your late model Benz in for a CEL... "Oh Mr. Customer, we have to take your engine out and apart.... 5 days and \$5K later... good as new"

And... What's to prevent the replacement components from wearing out the same way?... le...ls the problem "really" a faulty crafted part or is it a design issue?"

Finally, what other 06 models have the same 3.5L installed? the R, E, C classes ?

Jeff

'87 300E

'92 400E

'06 ML350

Quote

02-20-2010, 12:41 PM

Ruination Fan 👁 Registered User

Join Date: Jan 2008 Location: San Diego Posts: 56

The first run of production motors had a balance shaft gear that was too soft, and in turn the chain would wear it out prematurely. The new updated balance shaft gear has not shown any isssues.



(회 02-20-2010, 03:26 PM

#3

Ferdman 😘 Registered User

Join Date: Aug 2002 Location: Southeastern PA Posts: 1,605

Please explain what a balance shaft gear is. Never heard such a term before. Are you referring to a vibration dampener?

Fred Hoelzle



(a) 02-20-2010, 10:58 PM

Ruination Fan 🐯 Registered User

Join Date: Jan 2008 Location: San Diego Posts: 56

Its the gear that is mounted to the balance shaft, the balance shaft helps smooth out the v6 motor (believe It is a 90* V6, due to the modular construction) by using a counterweight. The gear is driven by the timing



(8) 02-22-2010, 08:14 AM

M.B.DOC @

Join Date: Mar 1999 Location: Tucker, Ga USA Posts: 10.513

Not just ML's but all MB's equipped with the M272/M273 series engines from 2005-08.

That is 1 of many reasons MB now suggests a maxi mun oil service of 10K miles as well.

MERCEDES Benz Master Guild Technician (6 TIMES) ASE Master Technician Mercedes Benz Star Technician (2 times)

40 years foreign automotive repair 27 Years M.B. Shop foreman (dealer)

MB technical information Specialist (12 years) 190E 2.3 16V ITS SCCA race car (sold)

1986 190E 2.3 16V 2.5 (sold)

mbdoc-pe@hotmail.com



Ø 02-24-2010, 03:37 PM

#6



Join Date: Feb 2000 Location: Canada Posts: 1,724

Worn gear replacement

I just had this done to my 2007 GL450, under warranty thank heaven! 🐯

It was a shock to visit the dealer and see my *new* GL sitting there with a gaping hole in the engine compartment! 🚱 🚳

Thankfully, they really took their time and the tech working on it was a senior tech with experience. They

had already done a few of these. They replaced a few other Items there as well, everything covered, including all the solenoid units. I took a look at the engine afterwards with a critical eye and things looked really good, nothing out of place.

I asked the tech if there were any stray bolts left at the end, he just gave me a look... 🏶

Talk about a massive job for a tiny part. He showed me the worn gear, the teeth were visibly worn, substantially so. The engine appeared to be in excellent shape otherwise, everything clean and no signs of wear.

Oh, and they also fixed my wouldn't-stay-shut coin tray.

C.

Chris

2007 E550 4Matic - 61,000 Km - Iridium Silver, black leather, Sport package, Premium package 2007 GL450 4Matic - 62,000 Km - Obsidian Black Metallic, black leather, all options 1998 E430 - for sale!

1989 300E - 333,000 Km - sold 1977 280E - sold

1971 250 - retired

"And a frign hat. They gave me a hat at the annual benefits meeting. I said, how does this benefit me. I don't have anything from the company.. So they gave me a hat." - TheDon



© 02-24-2010, 03:39 PM



Zeus & Moderating, Eh?

loin Date: Feb 2000

Location: Canada Posts: 1,724

Ouote:

Originally Posted by M.B.DOC 2

Not just ML's but all MB's equipped with the M272/M273 series engines from 2005-08.

That is 1 of many reasons MB now suggests a maxi mun oil service of 10K miles as well.

Are the shorter intervals supposed to help prevent wear on this part?

Any more insight on the M273 I should be aware of Doc? TIA.

Chris

2007 E550 4Matic - 61,000 Km - Iridium Silver, black leather, Sport package, Premium package 2007 GL450 4Matic - 62,000 Km - Obsidian Black Metallic, black leather, all options 1998 E430 - for sale!

1989 3006 - 333,000 Km - sold 1977 280E - sold

1971 250 - retired

"And a frign hat. They gave me a hat at the annual benefits meeting. I said, how does this benefit me. I don't have anything from the company.. So they gave me a hat." - TheDon



© 02-24-2010, 09:19 l™



Join Date: May 2000 Location: Location: Norcross, GA Posts: 77

Got the wife's ML back today... so far so good. The rap sheet i 5 pages of R&R this, R&R that, plus a list of every sleeve, seal and bolt you can imagine... Also replaced Oil Bump & pick up tube, balance shaft (of course), chain tensioner, cam plugs, valve timing solenoid units, every fluid that flows through its veins.

QUESTION - what's up with filling the engine with Mineral Oil, running, draining then changing the oil again and replacing the Mineral Oil with typical Synthetic? just curious what's special about MO?

Finally - what would happen if one did not have this issue resolved?

Jeff

'87 300E

'92 400E

'06 ML350





面 02-25-2010, 08:05 AM

M.B.DOC

Moderator

Join Date: Mar 1999 Location: Tucker, Ga USA Posts: 10.513

Using regular "mineral" oil is FINE...but oil change interval needs to be 5K miles not 10K!

Also in cold weather you might need to run lighter weight oil.

The timing chain can jump & bend all of the valves! Plus you wouldn't pass your emissions test.

MERCEDES Benz Master Guild Technician (6 TIMES)
ASE Master Technician
Mercedes Benz Star Technician (2 times)
40 years foreign automotive repair
27 Years M.B. Shop foreman (dealer)
MB technical information Specialist (12 years)
190E 2.3 16V ITS SCCA race car (sold)
1986 190E 2.3 16V 2.5 (sold)



(a) 02-25-2010, 11:17 AM



mbdoc-pe@hotmail.com

Join Date: Feb 2000 Location: Canada Posts: 1,724

Quote:

Originally Posted by jc300e 2

Got the wife's ML back today... so far so good. The rap sheet i 5 pages of R&R this, R&R that, plus a list of every sleeve, seal and bolt you can imagine... Also replaced Oil Bump & pick up tube, balance shaft (of course), chain tensioner, cam plugs, valve timing solenoid units, every fluid that flows through its veins.

QUESTION - what's up with filling the engine with Mineral Oil, running, draining then changing the oil again and replacing the Mineral Oil with typical Synthetic ? just curious what's special about MO?

Finally - what would happen if one did not have this issue resolved?

Exact same here, it's obviously the same procedure at all dealers. Same parts replaced, etc. They also did the multiple oil changes. I'm guessing that they do the initial quick run and drain to flush out any contaminants that may have entered the engine during the R&R. Hence the use of cheap oil. Since they are only using that oil change as a flush, why use full synthetic? Makes sense to use cheaper oil. Then they verify operation and no codes and then fill up with the proper oil and filter.

On one hand, it's sad to see such a beautiful piece of engineering in pieces! On the other hand, the engine gets an early mid-life inspection and you get all fluids changed (like compressor oil, refrigerant, antifreeze,

Chris

2007 E550 4Matic - 61,000 Km - Iridium Silver, black leather, Sport package, Premium package 2007 GL450 4Matic - 62,000 Km - Obsidian Black Metallic, black leather, all options

1998 E430 - for sale! 1989 300E - 333,000 Km - sold 1977 280E - sold

"And a frigh hat. They gave me a hat at the annual benefits meeting. I said, how does this benefit me. I don't have anything from the company.. So they gave me a hat," - TheDon



Join Date: Jan 2010

Posts: 2

Location: Obamanation

1 02-28-2010, 08:34 AM

1971 250 - retired

Darktech

Sagemeister

Here is what the offending part looks like and comparison pics:











1 02-28-2010, 08:36 AM

Darktech @

Sagemeister

Here is a link to the attached TSB document for your viewing pleasure: http://www.motor-talk.de/forum/aktio...hmentId=681441

Join Date: Jan 2010 Location: Obamanation

Posts: 2

% Ontole

(ii) 03-02-2010, 07:44 PM



eus 🛎 Moderating, Eh?

Join Date: Feb 2000 Location: Canada Posts: 1,724

Thanks Darktech, useful info.

2007 E550 4Matic - 61,000 Km - Iridium Sliver, black leather, Sport package, Premium package 2007 GL450 4Matic - 62,000 Km - Obsidian Black Metallic, black leather, all options

1998 E430 - for safe! 1989 300E - 333,000 Km - sold

1977 280E - sold 1971 250 - retired

"And a frign hat. They gave me a hat at the annual benefits meeting. I said, how does this benefit me. I dont have anything from the company.. So they gave me a hat." - TheDon



(B) 03-18-2010, 08:45 PM

#14




Join Date: Feb 2005 Location: Frederick, Md Posts: 4,493

View Photos By: Johnhef

Ahh the wonderful M27X balance shaft issue. I haven't had one in awhile so I'm probably due to get one. It's kinda like playing russian roulette when you get a m272/3 engined vehicle with the check engine light on. You have to ask yourself, "Do I feel lucky today?" and hope that the fault code turns out to be for just one of the cam adjuster solenoids and not the the fault codes-o-death, 1200 and 1208, indicating constant adjustment.

Anyways for anyone wondering the vehicles I've seen come through needing this have been mostly 2006-7 models but not limited to that as MBDOC said. ML350, R350, C230, S550, GL450 just to name a few. My experience has been limited to 2 GL450's and one ML350.



past; 1969 280SE 4.5 | 1978 240D | 1981 300SD | 1982 300CD | 1983 300CD | 1983 300SD | 1984 300D | 1984 300D | 1984 300D | 1984 300TD | 1984 500SEL | 1984 300SD | 1985 300D | 1986 300E | 1986 560SEL | 1986 560SEL/Carat | 1987 560SEC | 2006 R350

GWS-MBCA Vice President Join us! I am #H013278



#15

(8) 03-19-2010, 12:31 PM

1997 C36 AMG



Join Date: Sep 2002 Location: North Jersey, U.S.A. Posts: 1,775

I've got two at my shop right now, an ML and an R Class. It looks like two of my guys will be busy for the next few days. 📆 They're both out of warranty, but I'm sure MB will help out.

ILUVMILS
MB Shop Foreman
MB Master Technician
MB Master Guild Tehnician 2007
Factory trained in NJ, PA, AL, CA, FLA, and Germany



Past Reply

Page 1 of 2 1 2 > ♥

Case 2:10-cv-05130-DMC-JAD Document 28-1 Filed 12/01/11 Page 56 of 82 PageID: 576

Oals 252:10 How also constant a supplier of the contract of th

Bookmarks			
M Digg	≝g del.icio.us	StumbleUpon	Google


Ask a Mercedes Mechanic 8 Mercedes Mechanics Are Online! Ask a Question, Get an Answer ASAP. Mercedes Justo

Mercedes Benz Specialists Special Savings For Many Services. Your Mercedes Benz Repair Shop. EuropeanAutoRepr

Ada by Google

« Previous Thread | Next Thread »





All times are GMT -4. The time now is 07:41 PM,

-- Normal ShopForum Style

Contact Us - Homepage - Archive - Tot

Powered by vBulletin® Version 3.8.5 Copyright ©2000 - 2010, Jelsoft Enterprises Ltd.

PeachParts, LLC all rights reserved 1999 - 2010

PeachParts, LLC takes no responsibility whatsoever for any technical assistance offered by anyone. The Risk is 100% yours.

PeachParts is NOT affiliated, sponsored nor authorized by Daimler AG.

 Hom Buy Parl o Fastlan o AllPartsExpres o Special Too Shop Forus Resource o What's New o DIY Article o DIY Link o Good Shor o Featured Car

PeachParts Mercedes ShopForum > Technical Information and Support > ML,

User Name User Name

🙀 GL, G-Wagen, R-Class, Unimog, Sprinter 🕌 🚳 ML350 3.5L Balance Shaft Failure

Password

Remember Me?

Logility

Register

ShopForum Gallery

Calendar

Taday's Posts

Search

FAQ



Page 2 of 2 < 1 2 37

Thread Tools C7 Display Modes C7

2 03-19-2010, 12:54 PM



Zeus 👁 Moderating, Eh? Join Date: Feb 2000

Location: Canada Posts: 1,724

Quote:

Originally Posted by ILUVMILS 128

I've got two at my shop right now, an ML and an R Class. It looks like two of my guys will be busy for the next few days. M They're both out of warranty, but I'm sure MB will help out.

My tech was telling me about a colleague in LA (Benz tech) who said this repair was helping keep the dealership affoat with sales down! Lol...probably a bit of hyperbole, but there is likely some truth to it! 🕲

ILUVMILS - In your opinion as a tech, can the engine really be put back together as well as factory, assuming the tech working on it is experienced and competent? Just curious.

Chris

2007 E550 4Matic - 61,000 Km - Iridium Silver, black leather, Sport package, Premium package 2007 GL450 4Matic - 62,000 Km - Obsidian Black Metallic, black leather, all options

1998 E430 " for sale!

1989 300E - 333,000 Km - sold

1977 280E - sold

1971 250 - retired

"And a fright hat. They gave me a hat at the annual benefits meeting. I said, how does this benefit me. I don't have anything from the company.. So they gave me a het." - TheDon

髪 office

(Z) 03-19-2010, 10:06 PM



Join Date: Feb 2005 Location: Frederick, Md Posts: 4,493

View Photos By: Johnhef

The only ones MB hasn't helped out on at our place have been Carmax vehicles.



1980 500SE/AMG Euro

1981 300SD

1981 500SEL Euro

1982 380SEL 1983 380SEC

1983 500SEC/AMG Euro

1984 500SEC

1984 300TD Euro

1986 190E 2.3-16 1987 300D

1991 300D 2,5

1997 C36 AMG

past: 1969 280SE 4.5 | 1978 240D | 1981 300SD | 1982 300CD | 1983 300CD | 1983 300SD | 1984 300D | 1984 300D | 1984 300TD | 1984 500SEL | 1984 300SD | 1985 300D | 1986 300E | 1986 560SEL | 1986 560SEL/Carat | 1987 560SEC | 2006 R350

GWS-MBCA Vice President Join usl I am #H013278



函 03-20-2010, 12:00 PM



#18

Join Date: Sep 2002 Location: North Jersey, U.S.A.

Posts: 1,775

Quote:

Originally Posted by Zeus 23

....ILUVMILS - In your opinion as a tech, can the engine really be put back together as well as factory, assuming the tech working on it is experienced and competent? Just curious.

Yeah, we've been doing them for a couple of years now with no problems. It's really not that big a deal when you get right down to it. Of course, some guys like doing engine work, while others would rather replace an evaporator, or a windshield, etc. For this reason, less than half the balance shaft jobs in my shop are done by the tech who makes the original diagnosis.

ILUVMILS

MB Shop Foreman

MB Master Technician

MB Master Guild Tehnician 2007

Factory trained in NJ, PA, AL, CA, FLA,

and Germany



面 03-21-2010, 08:43 PM



#19

Join Date: Feb 2000 Location: Canada Posts: 1,724

Quote:

Originally Posted by ILUVMILS 図

Yeah, we've been doing them for a couple of years now with no problems. It's really not that big a deal when you get right down to it. Of course, some guys like doing engine work, while others

would rather replace an evaporator, or a windshield, etc. For this reason, less than half the balance shaft jobs in my shop are done by the tech who makes the original diagnosis.

Good to know, thanks for sharing.

That seems to be the same at my dealer's shop. The senior tech did my engine and another younger tech replaced a wiring harness and a DVD screen for the rear headrest entertainment unit.

When I went in to check on the progress, the engine was out and I was immediately impressed with how neat and organised all the disassembled parts were. The tech was obviously quite fastidious, which I appreciated and thanked him for.

Cheers,

C.

Chris

2007 E550 4Matic - 61,000 Km - Iridium Sliver, black leather, Sport package, Premium package 2007 GL450 4Matic - 62,000 Km - Obsidian Black Metallic, black leather, all options 1998 E430 - for sale!

1989 300E - 333,000 Km - sold

1977 280E - sold 1971 250 - retired

"And a frign hat. They gave me a hat at the annual benefits meeting. I said, how does this benefit me. I dont have anything from the company.. So they gave me a hat." - TheDon



(a) 03-29-2010, 11:06 PM

#20

billtinvegas 🌣 Registered User

Join Date: Mar 2010 Posts: 1

2006 R350 Blown Engine

My CEL had come on only once before and I limped to the MB dealer where I removed and resealed the gas cap and the car started right away with no problems. The Service Advisor took the car in to check for codes and came back saying that it didn't show anything. That was three months ago

Last Thursday driving on freeway at the end of a 150 mile trip the CEL came on and engine appeared to go into "limp" mode. As I decelerated and moved to right shoulder a crunching sound and LOTS of white smoke out the back. As I came to a stop and the smoke cleared I could see an oil slick marking my trail from where I heard the crunch.

The car has 89M miles and MB says they can't help - the dealer says it will be near \$20M to replace the engine! The dealer has done all recommended service at the recommended intervals. This was my first MB and I didn't buy the extended warranty.

I have asked for the error codes and if its the dreaded 1200 or 1208 do you think that the balance shaft gears being worn could have caused this?



3 03-30-2010, 08:13 AM

M.B.DOC @

Join Date: Mar 1999 Location: Tucker, Ga USA Posts: 10,513

Moderator

Run from that dealer!

I'm sure you can get a good used engine installed for less than 1/3 of that quote.

MERCEDES Benz Master Guild Technician (6 TIMES) ASE Master Technician

Mercedes Benz Star Technician (2 times)
40 years foreign automotive repair
27 Years M.B. Shop foreman (dealer)
MB technical information Specialist (12 years)
190E 2.3 16V ITS SCCA race car (sold)
1986 190E 2.3 16V 2.5 (sold)
mbdoc-pe@hotmail.com



Post Reply

Page 2 of 2 < 1 2 57

Bookmarks

g Digg

del.icio.us

StumbleUpon

Google

Save Hundreds on Your Auto Insurance

(8)



« Previous Thread | Next Thread »

Posting Rules

You may not post new threads You may not post replies You may not post attachments You may not edit your posts

BB code is On Smilles are On [IMG] code is On HTML code is Off

Forum Rules

Forum Jump

Mt., Gt., G-Wagen, R-Class, Ummog, Sprinter

ÇQ.

All times are GMT -4. The time now is 07:45 PM.

-- Normal ShopForum Style

Contact Us ~ Homepage ~ Archive ~ Tot

Powered by vBulletin® Version 3,8,5 Copyright @2000 - 2010, Jelsoft Enterprises Ltd.

PeachParts, LLC all rights reserved 1999 - 2010

PeachParts, LLC takes no responsibility whatsoever for any technical assistance offered by anyone. The Risk is 100% yours.

PeachParts is NOT affiliated, sponsored nor authorized by Daimler AG.

Material defects at Mercedes V6-/v8- Petrol Models-autobild.de.

http://www.autobild.de/artikel/mercedes-probeme-mit-v6-v8-benzinern...

Autobild.de

Mercedes: problems with V6-/V8 gasolines

Mercedes admits material fault



Mercedes has a problem with V6-/V8 motors. The owners are unhappy with the goodwill regulation. Dailmer promises improvements, however, questions still remain.

Owners of Mercedes six and eight cylinder engines still have to fear for their engines. Due to a material fault, on cars built between April 2004 until September 2006, a gearwheel of the timing chain can wear down. The damage is noticeable when the engine indicator lamp is on. Repairs cost up to 4700 Euros, depending on the model. Mercedes has built the engines of series M272 (2.5, 3 and 3.5 liter V6) and M273 (5 liter V8) in ten model ranges. It's still a mystery how many cars with M272 and M273 engines have been affected by this fault.

Overview: all news and tests on the Mercedes brand

Material defects at Mercedes V6-/v8- Petrol Models-autobild.de.

http://www.autobild.de/artikel/mercedes-probeme-mit-v6-v8-benzinern...

A company spokesman has declared for AUTO BILD that, until now, there is a "very low failure quota, of about one percent" - around 1500 fault cases. They estimated that there would be very few new complaints and that most cases have already been handled. This is the result of an internal faults statistic - which is, however, kept classified by Mercedes. Apparently, it can't be predicted which cars will be affected by this problem. The reason: in case of chain wheels made of sintered steel, different material compositions are used. This problem was solved only after chain wheels were once again made of conventional steel (September 2006).



The CLS owned by Manfred Obrist from Baden broke down at 102.000 kilometers.

Mercedes incresed the goodwill expenses percentage. However, costs amounting to 1000 Euros still remain.

Page 1 of 4

In case of damage (check engine light is on), the manufacturer advises owners to only use a Mercedes garage instead of going to a general car workshop. Firstly, only then can costs be reduced and, secondly, goodwill compensation could be handled. Furthermore: customers, who are not satisfied with the cost-sharing of Mercedes, can apply for a new goodwill compensation, which will be verified once again. Both the mileage and goodwill limits have now "been considerably expanded".

Material defects at Mercedes V6-/v8- Petrol Models-autobild.de.

http://www.autobild.de/artikel/mercedes-probeme-mit-v6-v8-benzinern...

Comments of Matthias Moetsch

"This fault refers to the very core of Mercedes. This is about thick gasoline-operated engines. About cars that costs around EUR 70,000 - 100,000 or even more. About customers, who especially leave lot of money in the company's cash office: car lovers, solvent owners, regular customers. They now drive with the uncertainty that at a certain point in time, their engine will break down. For a producer who advertises "The best or nothing at all" on banners, from the point of view of this clear failure, the can be only one answer: 100 percent compensation for everyone. Everything else is nothing at all."

autobild.de

Mercedes: Probeme mit V6-/V8-Benzinern — 04.08,2011

Mercedes gibt Materialfehler zu

Google Anzeige

German Car Experts Housto

We are your dealership alternative Certified Technicians, repairs www.lgautorepair.com




Mercedes hat ein Problem mit V6- und V8-Motoren. Die Besitzer sind unzufrieden mit der Kulanzregelung. Daimler gelobt Besserung, doch es bleiben Fragezeichen.

Besitzer von Sechs- und Achtzylinder-Benzinern von Mercedes müssen weiter um ihre Motoren bangen. Wegen eines Materialfehlers kann sich bei Autos des Bauzeitraums April 2004 bis September 2006 ein Zahnrad an der Steuerkette abnutzen. Der Schaden kündigt sich mit dem Aufleuchten der Motorkontrollleuchte an; die Reparatur kostet je nach Modell bis zu 4700 Euro. Mercedes verbaute die Motoren der Baureihen M272 (2,5-, 3,0- und 3,5-Liter-V6) und M273 (5,0-Liter-V8) in zehn Modellreihen. Wie viele Autos mit M272- und M273-Motor von den Schäden betroffen sein können, bleibt weiter im Dunkeln.

Übersicht: Alle News und Tests zur Marke Mercedes

Ein Firmensprecher sagte gegenüber AUTO BILD, dass es bislang "eine sehr gerlnge Ausfallquote von ca. einem Prozent" gebe – rund 1500 Schadensfälle. Man rechne nur noch mit wenigen neuen Beanstandungen, die meisten Fälle seien bereits abgearbeitet. Dies ergebe sich aus einer internen Mängelstatistik – die Mercedes allerdings unter Verschluss hält. Bei welchen Fahrzeugen das Problem auftritt, lässt sich offenbar nicht vorhersagen. Grund: Beim Kettenrad aus Sinterstahl seien verschiedene



gekommen. Erst seit wieder Kettenräder Kosten blieben. aus konventionellem Stahl eingebaut wurden (September 2006), war das Problem gelöst.

VW: Rückruf wegen weicher Zahnräder

Ende 2008 rief der VW-Konzern rund 25.000 Passat und Sharan mit 2.0-TDI-Motor in die Werkstätten, weil es zu "vorzeitigem Verschleiß der Zahnräder im Ausgleichswellenmodul" kommen konnte. Die Zahnriemen-TDI von VW besitzen zwar keine Steuerkette, die Ausgleichswelle wird jedoch über Stirnräder angetrieben. VW-Sprecher Harthmuth Hoffmann zu AUTO BILD: "Die Werkstattaktion wurde präventiv durchgeführt, um größere Schäden zu vermeiden."

Im Schadensfall (Motorkontrollleuchte brennt) rät der Hersteller, unbedingt eine Mercedes-Vertretung aufzusuchen und keine freie Werkstatt. Nur so könnten zum einen Kosten begrenzt und zum anderen ein Kulanzantrag bearbeitet werden. Und: Kunden, die mit der Kostenbetelligung von Mercedes unzufrieden sind, können einen neuen Kulanzantrag einrelchen, dieser würde noch einmal geprüft. Sowohl die Kilometerleistung als auch der Kulanzrahmen seien nun "deutlich erweltert worden".

Kommentar von Matthias Moetsch



"Dieser Fehler trifft Mercedes ins Mark. Es geht um die dicken Benzinmotoren. Um Autos, die 70.000, 100.000 Euro oder mehr kosten. Um Kunden, die besonders viel Geld in der Konzernkasse lassen: Autoliebhaber, solvente Herrschaften, Stammkunden. Sie fahren nun mit der Ungewissheit, Irgendwann einen Motorschaden zu erleiden. Für einen Hersteller, der sich "Das Beste oder nichts" auf die Fahnen schreibt, kann es angesichts des klaren Versagens nur eine Antwort geben: 100 Prozent Kulanz für alle. Alles andere ist nichts."

M. Moetsch

Lesen Sie auch: Mercedes-V-Motoren für die Zukunft

Google Anzelgen

ermatec AG, Ermatingen

Fördertechnik, Mühlenbedarf Elevatorbecher, Schneckenflügel uvm www.ermatec.ch

Energieführungs-Systeme

Energieführungen aus Stahl, Kunststoff und Hybrid www.kabelschiepp.de

Mercedes Body Repair

Houston Auto Body Repair Experts. Certified In Luxury Auto Brands. www.HanleyBros.com

Mehr zum Thema

Suchbegriff eingeben



Kommentare z	um Artikel (55) 🐆	
Das sehen Sle auch so? Oder anders? Diskutieren Sie mit!		
Erstellt	Text	Funktion
	@ Willkommen im Club	
Kochender,		
07,10,2011 18:24Uhr	Das ist ja wirklich der Hammer, das Kettenrad muss nun aus purem Gold seln. Ich denke da bleibt dir genau wie mir nichts anderes übrig als den Weg zum Anwalt anzutreten.	Eintrag melden
Willkommen-	Es wird immer doller!	
lm-Club,		Eintrag
05.10,2011 15:02Uhr	Ich habe eben mit meiner Werkstatt telefoniert: die Rechnung beläuft sich auf sagenhafte 6.500 EUR!	melden
Kochender, 15.09.2011 17:57Uhr	Mercedes will mit dem Eigenanteil von 25 % eventueil seine Eigenkosten decken, dies hat mir ein Außendlenstmitarbeiter von MB als "Theorie" erzählt. Am Anfanf stand der CLS 350 noch mit 3000,-, jetzt wo sich die Fälle häufen gehen die Kosten plötzlich auf 4500,- und mehr nach oben.	Eintrag melden
	Seite 1 2 3 4 5 6 7 8 9 10 11	nächste


Seite >

- Home
- About
- Privacy Policy
- Contact Us

« <u>Video: Trailer for 'Need For Speed: The Run' hits the web Video: Lamborghini Murcielago LP640 Roadster in Heavy Rain – FAIL – GT News »</u>

<u>Mercedes Hit With Timing Chain Issues on 2004-2006 V6 and V8 Models – Auto Industry News</u>

August 5th, 2011 | Author:



Mercedes-Benz is currently trying to recapture the number one position in global luxury sales, but a quality problem on its home turf in Germany seems to be undermining confidence in the brand. Autobild reports that the M272 V6 and M273 V8 engines used a sintered steel timing chain gear made of various materials starting in 2004, but switched to conventional steel in 2006, eliminating the problem with gear wear. The problem nobody seems to know how many vehicles built between 2004 and 2006 are affected. Mercedes claims, based on secret internal defect tracking, that one percent, or about 1,500 vehicles, are affected. If you have a vehicle with one of these engines built between 04 and 06 and your check engine light comes on, Mercedes encourages you to visit your M-B dealer rather than an independent shop, as Mercedes is offering free repairs to affected customers. And as Autobild's Matthias Mötsch argues, when your motto is "the best or nothing," the only answer to a situation like this is to fix 100% of the defects for free.

Pages

- About
- Contact Us
- Privacy Policy

Like



The Truth About Cars

shopautoweek.com

shopautoweek.com matches your needs with expert car advice






Tags: 20042006, Auto, Chain, Industry, Issues, Mercedes, Models, News, Timing

[C] Posted in Automobile Reviews | C Tags: 20042006, Auto, Chain, Industry, Issues, Mercedes, Models, News, Timing

2006 MERCEDES-BENZ M-CLASS



Kelley Blue Book \$23,500 - \$24,300 Reliability rating

MSN ratings & reviews

User rating: Read reviews MSN autos rating: 8.0 Read reviews New Mercedes C Find Mercedes C Dealers and Get a Local Quote Today! Mercedes Auto-Price-Finder.com

Mercedes C-Class Prices

Find out the Dealers' Secret Price on an All-New Mercedes.CarPriceSecrets.com

For Sale - Used C-Class

Search over 4030 used Mercedes-Benz C-Class. Prices starting at \$3,990 www.CarGurus.com/Mercedes-Benz

Need car insurance?

Find savings in your neighborhood with our discounted policy finder.
AutoInsuranceHintsTipsandNews.com

AdChoices D

2006 MERCEDES-BENZ M-CLASS

By Dan Jedlicka of MSN Autos

Rating: 8

Bottom Line:

The second-generation M-Class promises to be extremely competitive

- · Thoroughly redesigned
- Sleeker
- Roomier

- Tricky gear changer PICTURES
- Rather high cargo floor
- · Shallow rear cupholders

'our email

RECENTLY VIEWED CARS



SEE COMPETITORS

2006 MERCEDES-BENZ M-CLASS See Competitors

View favorites

The redesigned second-generation Mercedes-Benz M-Class sport-utility vehicle is a major improvement over the first-generation model. It's sleeker, larger and—importantly—far more carlike, as are most new

This early 2006 M-Class has some of the boxy 1998-2005 model's design language, but is much more streamlined with such things as a swept-back windshield, and alluring blend of strongly contoured surfaces and faul lines. The roomier interior also gets a much-needed update, Like the first-deneration M-Class, the 2006 model is built at Mercedes' Tuscaloosa, Alabama plant.

Mercedes introduced the new M-Class far from Alabama at a media preview drive in Provence, France starting in Nice and involving challenging mountain driving.

Exact prices weren't announced at the preview, but Mercedes said they'll range from approximately \$40,000 to the high-\$40,000 range when the two M-Class versions go on sale in April. The 2005 M-Class has list prices of \$37,950 and \$46,400

Two Trim Levels

The 2006 M-Class is packed with comfort, convenience and safety features. It comes in two trim levels: the ML 350 with a 3.5-liter V6 generating 268 horsepower---or 36 more than the current V6-- and the ML 500 with a 5.0-liter V8 with 302 horsepower, up from 288.

A hot rod AMG version of the M-Class may arrive next year with racy cosmetic touches and a rumored 500-horsepower V8. Also, an advanced turbocharged diesel engine is scheduled to be offered in 2007 for sale in most areas of the country except California and a few northeastern states

Many may have forgolten that most Mercedes cars sold in America a few decades ago had diesel engines, which are popular in Europe because of advanced new diesel designs and sky-high gasoline prices.

The ML 350 provides decent acceleration and is expected to account for 75 percent of sales, with the V8 picking up the rest. However, the M-Class is heavy at approximately 4.800 pounds, so the V8 provides the best acceleration

World-First Transmission

The new M-Class engines work with the world's first 7-speed automatic transmission, instead of a typical 4- or 5-speed automatic. The more gears with an automatic, the better responsiveness and fuel economy.

A "Direct Select" feature lets the transmission be electronically touch-operated by nudging a steering column stalk that doesn't take up space like a floor-mounted shifter. But the stalk can be tricky to use if a driver is in a hurry. For instance, it requires more than lazy concentration to select a gear, and the "park" gear position is gotten by pushing in the stall.

RELATED ARTICLES

IIHS's Top Safety Picks Auto Show Trend: Crossovers/SUVs SUVs Go Upscale 500-Horsepower Club



Mercedes called the first M-Class an "All Activity Vehicle." It was a new type of vehicle for Mercedes and one of the first mid-size luxury SUVs. It had Mercedes' first V6 engine and was the first Mercedes built in

Being the first Mercedes luxury SUV, the 1998 M-Class had several glitches. For example, folding the 3plece rear seatbacks forward for more cargo room required working awkward-to-use cheap plastic levers and releases—and then the seatbacks didn't fold flat. Many owners must have shook their heads and said, "This is a Mercedes?" However, the SUV was improved as the years passed.

Many Rivals

"The first M-Class had little competition when it came out, But M-Class rivals now are all over the place." said Mercedes-Benz USA M-Class product manager Ron Mueller.

The 2006 M-Class will mainly compete with BMW's X5 SUV, but also faces upscale rivals from automakers including Acura. Cadillac, Infiniti, Lexus and Volvo.

"The 2005 M-Class really isn't unusually old for a Mercedes because the life cycle of most of our models is about 7.5 years," said Mercedes spokesman Rob Moran

However, Morcedes says it may have to shorten vehicle life cycles because of greater competition.

More Modern Feel

The new M-Class feels a lot more modern than its predecessor. Trucklike body-on-frame construction has been replaced by a rigid car-like unibody platform. The new model is 5.9 inches longer, 2.6 inches wider and a little lower. The T14-inch wheelbase is nearly 4 inches longer for a more comfortable ride.

Test drives on twisting mountain roads showed the M-Class to have quick steering with Mercedes' slightly heavy, but reassuring, feel. The brake pedal initially felt a little touchy, but I soon got used to it and appreciated the strong brakes. Road manners were very sporty for a heavy SUV.

The ride was comfortable, and the new Mercedes looked right at home while cruising through glamorous French cities such as Nice and Cannes

Off-Road Abilities Downplayed

The 2006 M-Class retains good off-road prowess with its standard all-wheel-drive system, but it's mainly designed for on-road driving

"Less than one percent of SUV owners use their vehicles for tough off-road motoring," Mueller said, "That's why an optional off-road suspension package will not be offered for the M-Class in America until 2007."

Gauges can be quickly read and dashboard controls are easy to use—as are power seat controls on the sides of the supportive front seats

Traction control and anti-skid systems are standard, as are anti-lock brakes with an assist feature for

Roomy

The quiet, upscale interior has good room for four tall adults. The front console has two deep cupholders, but rear cupholders in the fold-down armrest are shallow.

Optional features include "Keyless-Go." which allows doors to be opened and the M-Class to be started without a key: a driver only needs to keep the vehicle's key fob in a pocket or purse and just pushes a button to start and to stop the engine.

The optional power tailgate opens easily to reveal a large cargo area, although it has a rather high opening. The entire rear seats flip forward to enlarge the cargo area—and this time Mercedes got it right because that's a no-sweat procedure

Twin hydraulic struts let the hood raise smoothly, which shows good attention to detail.

Mercedes has had quality issues in the past few years, but feels confident that the new design of the solid-feeting M-Class should be free of problems.

2006 MERCEDES-BENZ M-CLASS COMPETITORS

Acura MDX BMW X5 Cadillac SRX Chevrolet Tahoe Infiniti FX Jeep Grand Cherokee Land Rover LR3 Land Rover Range Rover Land Rover Range Rover Lexus GX 470 Lexus RX 330 Lexus RX 400h Sport Porsche Cayenne Toyota Land Cruiser Volkswagen Touared Mercury Mountainee Volvo XC90

Case 2:10-cv-05130-DMC-JAD Document 28-1 Filed 12/01/11 Page 73 of 82 PageID: 593 2006 Mercedes-Benz M-Class Expert Review - MSN Autos Page 3 of 3

Competitive analysis: We compare all 17 competitors for you	u	
Compare 2006 Mercedes-Benz M-Class photos		
Compare 2006 Mercedes-Benz M-Class specifications		
MSN privacy Legal Advertise RSS		© 2011 Microsoft

BB02 - 11/21/2011 1:47:25 PM



Smarter commerce creates new opportunities.



Register

Andrew Business News Monada Tom Stord February Tech Persona February Small Resonance

SObmition

: Analysis from FORTUNE: Plugged In

■ Column archive

Mercedes vs. Consumer Reports

The luxury carmaker is not happy with recent rankings that appeared in the 2007 New Car Preview

By Alex Taylor III, Fortune senior editor November 20 2006: 9:11 AM EST

FORTUNE

NEW YORK (Fortune) - There is an old saying in the newspaper business that you shouldn't pick a fight with somebody who buys ink by the gallon.

That hasn't stopped Mercedes-Benz from taking a few swipes at Consumer Reports over some very damaging reviews of Mercedes vehicles

First some background: For the 2007 edition of its New Car Preview, Consumer Reports surveyed its six million subscribers about what serious problems they had with the cars they own. Some 1.3 million responded and the results weren't good for Mercedes-Benz.

Here's a brief blow-by-blow: In a listing of the least reliable fuxury cars, based on 2006 models, three of the six cars are Mercedes: the old S-class (prior to the recent redesign), the CLS and the E-class

Most and least reliable cars

Same thing in sport cars. Mercedes hogged three of the seven slots for least reliable: the SL, the CLK and the V6 SLK

More from Fortune

In Spain, new leadership, same problems

Meg Whilman on easing HP's "nost-traumatic stress

Startup lessons from the global debt crisis

FORTUNE 500

Current Issue

Subsaribe to Fortuna

Among mid-sized SUVs, the M-class, a quality disaster when it first came out, still ranks as the least reliable in its arouping.

Other luxury manufacturers turn up on the least reliable list, with BMWs, Jaguars and Cadillacs sprinkled throughout

But what is striking about Mercedes' performance is its consistency. Of the 11 models reviewed by Consumers, none are recommended. Seven are left off of the list because of poor reliability; the remaining four are considered too new to predict.

Mercedes has the worst record of any automaker with that many models. For a brand that claims to be "engineered like no other car in the world," that is fairly frightening.

"They understand the problems and they are fixing some of them, but they have a long way to come," says David Champion, director of automotive testing at Consumers.

For its part, a spokesman for Mercedes says that the date in the Consumer Reports rankings "is totally out of sync with what we're seeing in the mainstream research as well as our own customer satisfaction and warranty data." He points to the good marks Mercedes gets for ride, handling, comfort, safety and


He may be whistling into a windstorm, though. "Car buyers pay a lot of attention to CR's ratings," says industry consultant George Peterson. "They perceive them as unbiased."


Research by Peterson's own firm, AutoPacific, substantiates CRs findings. Its 2006 Ideal Vehicle Awards show Mercedes not only ranking ninth out of ten among tuxury brands but also lower than the top ten mainstream brands like Hyundai (Charls) and Subaru.

Quality problems have been a big issue at Mercedes for several years and the company keeps insisting it has a handle on them. But issues keep cropping up.

The JD Power Initial quality study for 2006 models, which measures defects identified by customers during the first 90 days of ownership, put Mercedes at 25th out of a field of 37 brands. That was well behind leaders like Porsche, Toyota's (Charts) Lexus, Jaguar, GM's (Charts) Cadillac and Infiniti, though still two notches

The Mercedes spokesman blames that low ranking on two major complaints: brake dust from the high performance brakes and problems with the new seven speed transmission, that he says have been repaired.





YOUR E-MAIL ALERYIS

Follow the news that matters to you, Condenses our alert to be notified on topics you're interested in.

Or, visit Papaller Aforts for suggestions.

Manage aterts I What is this?

He adds: "As you're aware, the IQS included a new survey methodology by JD Power which goes well beyond the actual quality of the vehicles and Into subjective measurement (an important distinction) of how customers feel about such things as the design, look and operation of features, controls and equipment."

Mercedes still makes superb automobiles - striking in design, sophisticated in engineering, exhilarating in performance. It attracts hugely loyal buyers and its cars retain value better than most.

But being a leader means being constantly under attack by those behind you. Along with BMW and Lexus, Mercedes ranks in the top tier of lexury brands.

But until it can tame the devilish complexity of its cars into more reliable transportation, its position will remain precarious. And it doesn't help to be in denial about the problems you face - or to attack the messenger who delivers the bad news.

Most reliable cars. Consumer Reports: Ford's (Charts) new sedans shine in results, but Japanese still most reliable by far. ■

SAVE | EMAIL | PRINT | KSS | REPRINT

More Autos

Sweet rides from the L.A. Auto Show

John Smale: GM's pioneering director dies at 84

Honda Civic Natural Gas: Green Car of the Year

The Hot List

100 best places to start a business

Diesel: The truck stops here

'You're working for gas now'


CONTRACTOR

About CNNMoney	Content	Magazines	Site Tools	Stay Connected
Contact Us	Fortune Magazine	Subscribe to Furlane	Sile Map	My Account
Advertise with Us	Money Magazine	Subscribe to Money	Watchlist	Mobile Site & Apps
User Protorences	Business News	Give the Gift of Fortune	Search Jobs	Facebook
Career Opportunities	Markets	Give the Gilt of Money	Real Estate Search	Twiller
Conferences	Term Sheet	Reprints	Mortgage and Savings Center	Linkedin
Business Leader Council	Economy	Special Sections	Calculators	YouTube
	Tech	Magazine Customer Service	Widgets	RSS Feeds
	Personal Finance		Corrections	Newsletters
	Small Business		Market Data Alerts	Tumbk
	Video		News Alerts	

Market indexes are shown in real time, except for the CJIA, which is delayed by two minutes. All times are ET. Disclaimer LIBOR Warning. Neither BBA Enterprises Limited, nor the BBA LIBOR. Continuer Banks, nor Reuters, can be field liable for any irregularity or inaccuracy of BBA LIBOR. Disclaimer, Manningstar \$2011 Morningstar, Inc. All Rights Reserved, Disclaimer The Dow Jones IndexesSM are progretary to and distinituded by Dow Jones & Company, Inc. and have been licensed for use. All content of the Dow Jones indexesSM \$2011 is proprietary to Dow Jones & Company, inc. Chesgo Mercantile Association. The market data is the property of Chesgo Mernantly Exchange Inc. and its licensers. All rights reserved, FactSet Research Systems Inc. 2011. All rights reserved. Most block quote data provised by BATS.

^{😌 2011} Cable Nows Network, A Time Warner Company. All Rights Received, Tarms under which this service is provided to you. Privacy Policy, Ad choices 🕩

Case 2:10-cv-05130-DMC -JAD Document 19-2 Filed 03/28/11 Page 6 of 73 PageID: 304



Service and Warranty Information 2006 Trucks
M-Class, R-Class, G-Class



Case 2:10-cv-05130-DMC -JAD Document 19-2 Filed 03/28/11 Page 20 of 73 PageID: 318

Service and Warranty

Limited Warranty - 2006 Registration Year Trucks

Items Which Are Covered;

DEFECTS: Mercedes-Benz USA, LLC (MBUSA) warrants to the original and each subsequent owner of a new Mercedes-Benz truck that any authorized Mercedes-Benz Truck Center will make any repairs or replacements necessary, to correct defects in material or workmanship arising during the warranty period.

ANY MERCEDES-BENZ TRUCK CENTER: Any authorized Mercedes-Benz Truck Center of the owner's choice will perform warranty repairs or replacements. The vehicle should be delivered to the Mercedes-Benz Truck Center during normal service hours. A reasonable time should be allowed after taking the truck to the Mercedes-Benz Truck Center for performance of the repair.

WARRANTY PERIOD: This warranty is for 48 months or 50,000 miles, whichever occurs first.

WARRANTY STARTS: The warranty period starts on the date the truck is delivered to the first retail purchaser or put in service as a Mercedes-Benz Truck Center demonstrator or Mercedes-Benz U.S. International, Inc. (MBUSI), Mercedes-Benz Service Corporation (MBSC) or Mercedes-Benz USA, LLC (MBUSA) company truck.

WHEEL ALIGNMENT AND BALANCING: Wheel alignment and wheel balancing are covered during the first 12 months or 12,000 miles, whichever comes first, and will be performed by any authorized Mercedes-Benz Truck Center.

TIRES: The tires supplied on your truck are covered against defects in material or workmanship for the Mercedes-Benz New Truck Limited Warranty period of 4 years and/or 50,000 miles from date of delivery or when the truck was put in service. Should the tire become unserviceable for either of the above reasons, the tire will be

replaced free of charge, including mounting and balancing, provided 1.6 mm of tread depth remains over the entire tread surface. Any tire replaced under warranty will be covered for the remaining portion of the New Truck Limited Warranty period only.

The tire manufacturer's warranty coverage may extend beyond the Mercedes-Benz New Truck Limited Warranty. See tire manufacturer's warranty booklet in the owner's literature package or consult with the tire manufacturer's dealer for specific details.

Tire rotations, if applicable to your vehicle tire configuration, are a required maintenance service. Not performing tire rotations may void the Mercedes-Benz tire warranty coverage. See page 7 for information on the First Tire Rotation provided at no charge at an authorized Mercedes-Benz Center courtesy of Mercedes-Benz.

Case 2:10-cv-05130-DMC JAD Document 25 Filed 08/23/11 Page 9 of 10 PageID: 503

Practical hints

What to do if ...

appear in the multifunction display located

in the instrument cluster.

Warning and malfunction messages

Vehicle status messages in the

multifunction display

Certain warning and malfunction messag-

Address these messages accordingly and es are accompanied by an audible signal.

follow the additional instructions given in

this Operator's Manual.

(> page 159) displays both cleared and

uncleared messages.

High-priority messages appear in the

multifunction display in red color.

Selecting the vehicle status message

memory menu in the control system

button 😂 , 🔁 , 📹 , or 📻 on the be cleared from the multifunction display Certain messages of high priority cannot using the reset button (> page 24) or multifunction steering wheel.

clearing a message will only make the mes-Other messages of high priority and mesthen stored in the vehicle status message button 🐼 , 🗘 , 🛋 , or 🖼 on the not correct the condition that caused the sage disappear. Clearing a message will sages of less immediate priority can be multifunction steering wheel. They are memory (> page 159). Remember that cleared from the multifunction display using the reset button (> page 24) or message to appear.

Limited Warranty, or result in property dam-Failure to repair condition noted may cause damage not covered by the Mercedes Benz taken note of and, where a malfunction is indicated, addressed as soon as possible; an authorized Mercedes Benz Light Jruck important information which should be All categories of messages contain. age or personal injury. Warningt Center.

No messages will be displayed if either the Warningt play is inoperative. いくいあがける

instrument cluster or the multifunction dis-Weroedes-Benz Light Truck Center Contact the nearest authorized